FAULKNER COUNTY JIM B. BAKER COUNTY JUDGE

801 Locust Street • Conway, AR 72034



MARGARET DARTER FAULKNER COUNTY CLERK
BY Walter DC

IN THE COUNTY COURT OF FAULKNER COUNTY, ARKANSAS COURT ORDER NO. 22- 07 \

IN THE MATTER OF REMOVAL OF COUNTY PROPERTY FROM FAULKNER COUNTY INVENTORY

After having reviewed the documents provided by the Faulkner County Assessor's Office, the County Court hereby Finds and Orders as follows:

The vehicle listed below is considered a total loss due to an accident. Therefore, the vehicle listed below needs to be removed from county inventory.

Department: Sheriff's Office

Item Description

VIN/Serial No.

Inv. No.

Tag No.

Est. Value

2018 Dodge Charger

2C3CDXAG3JH253319

V.2.114

IT IS SO ORDERED

Jim/B. Baker

Faulkner County Judge

March 30, 2022

FAULKNER COUNTY ASSESSOR'S OFFICE KRISSY LEWIS, ASSESSOR

806 FAULKNER STREET CONWAY, AR 72034 PHONE (501) 450-4905 FAX (501) 450-4908

E-MAIL krissy.lewis@faulknercounty.org

March 25, 2022

Jim Baker, Faulkner County Judge Angie Wooley, Faulkner County Sheriff's Office

RE: Inventory

Dear Judge Baker & Ms. Wooley

The Faulkner County Assessor's Office has been asked to prepare a letter to remove the following vehicle from County Inventory for the Sheriff's Office. According to the appraisal evaluation, the vehicle is considered a total loss due to an accident. Therefore, the vehicle listed below needs to be removed from County Inventory.

Item Description 2018 Dodge Charger VIN Number 2C3CDXAG3JH253319

Inventory Number V.2.114

Respectfully,

Donna Beck Chief Deputy Assessor





Sheriff Tim Ryals

Chief Deputy Chad Wooley

March 23, 2022

Jim Baker, County Judge

Krissy Lewis, County Assessor

Dear Judge Baker & Ms. Lewis,

auxi Doley

I am requesting that the County Judge order the following property listed below to be removed from the inventory list for our department:

| <u>Item</u> | Serial/VIN # | Inventory | Tag | Reason for Removal |
|-------------|-------------------|-----------|-----|-----------------------|
| Description | | <u>#</u> | # | |
| Unit# 1808- | 2C3CDXAG3JH253319 | | | Totaled 3-5-2022, AAC |
| 2018 Dodge | | | | PAID CK#20497, AAC |
| Charger | | | | Claim# AAC-0039445, |
| | | | | Treasurer's Receipt# |
| | | | | 19779 |

Sincerely,

Angie Wooley Fiscal Officer

INVENTORY CONTROL RECORD

| Dept No. | 0436 | | _Date of PO | | |
|---------------|---------------|-------------------|--|--------------|-----------|
| Check One: | Acquisition: | Transfer: | | Disposed of: | X |
| Description: | 2018 Dodge (| Charger | | | |
| Serial No. | 2C3CDXAG3JI | 1253319 | | | |
| Purchase Pric | e or Value \$ | \$21,339.00 | ************************************** | Date: | 3/21/2022 |
| Comments/Lo | | Totaled 3-5-202 | | CK# 20497 | |
| AAC Claim# A | AC-0039445, 1 | reasurer's Receip | ot# 19779 | | |
| | | | | | |
| Signature: | Capil | Dooley | | | |
| Fund# | 3407.0436.40 | 04 | Claim# | | |

Treasurer Scott Sanson 801 Locust Street

CONWAY, AR 72034

Treasurer's Receipt

Receipt Number: 19779

page 1 of 1

Entry Date:

03/21/2022

Received From:

Association of Arkansas Counties

Source:

Total Loss Settlement 2018 Dodge Charger #3319

FCSO Claim #AAC-0039445

Unit #1808

Receipt Date:

03/21/2022

Cashier:

Angie Casey

| Payment Type | Amount | Account # | Description | Amount |
|--------------|-----------|-----------|--------------------|-----------|
| CK 20497 | 21,339.00 | 3407.8718 | Insurance Proceeds | 21,339.00 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | * 9 | | |
| · | | | | |
| | | | | |
| | | | | |
| | | | | |

Authorized Signature: Scott Somsoma

Total Receipt: 21,339.00



ASSOCIATION OF ARKANSAS COUNTIES

RISK MANAGEMENT FUND/CLAIMS ACCT. 1415 WEST THIRD STREET LITTLE ROCK, ARKANSAS 72201

BANK OZK 81-727/829

PAY

Twenty One Thousand Three Hundred Thirty Nine and 00/100 dollars

DATE

AMOUNT

TO THE ORDER OF

Faulkner County C/O Jim Baker, County Judge 03/15/2022

\$21,339.00

801 Locust St.

Conway, AR 72034

VOID AFTER 60 DAYS

#O2049?# #OB290?2?3# 203801?253#

20497

Faulkner County C/O Jim Baker, County Judge 801 Locust St. Conway, AR 72034

20497

Member

Faulkner County - Sheriff's Dept.

Claimant

Sheriff Dept. Faulkner County

To sond 2401

Check Amt: \$21,339.00

Check Date: 03/15/2022

Claimant: Sheriff Dept. Faulkner County

Claim No: AAC-0039445

Date of Loss: 03/05/2022

Adjuster:

Riley Groover

Invoice Number:

Payee Name:

Faulkner County

Payment Type:

Total Loss (Collision) 2022-03-15 thru 2022-03-15

Service Dates: Whit # 1808

Payable Comment

Total Loss Settlement 2018 Dodge Charger #3319 (less \$500 deductible)

881004/04-16

6221360600 B943E8 CHIKDK05 06/07/2021 18:23 -6

CRASH REPORT - CRASH SUMMARY

| | Drivers' Las | t Names | EVANS, MA | HER | | | | | | | | | Page | 1 of 13 |
|----------------|---|-----------------------------------|---|---|-------------------|---|----------|--------------------------------|---|-----------|-------------|-----------------------------------|-------------------------------------|---------|
| | Juvenile Inve | olved 🔲 | Yes 🗹 No | ARKA | NSA | AS MOTOR VE | HICL | EC | RASH REP | ORT | Sever | ity 🗆 Fa | atality 🗹 Injury | |
| * | of Motor Vehicles Automobiles, Motorcycles, e | etc. 2 | | | | | 2019-1 | | Crash Report | | | | , | |
| # | of Non-Motorists | 0 | Investi | gating Ager | icy S | TATE POLICE TROO | PA | | | | | | | |
| | | CPL | HOWING | GTON | | JOHN | | | 443 | Sig | nature | | | |
| | nvestigating Office | Rank | Last | | | First | М | liddle | Suffix Badge | ' | | 6 | IL IL | |
| | | Ser Line | | 11567 | | CRASH DAT | EAN | D TIN | ME | | | | | Vi |
| | Date of Crash (MM/D | ד מייייסס | ime of Cra | , | AM/PM) | Date Police Notifie | d T | ime P | olice Notified | Date Poli | ce Arr | ived | Time Police A | rrived |
| | 03/05/2022 | | 1 | 0:06 PM | | 03/05/2022 | | | 10:11 PM | 03 | /05/20 |)22 | 10:22 F | РМ |
| | County | | | Sit. | | CRASHL | OCAT | A COLUMN TWO IS NOT THE OWNER. | | | | | | |
| | aulkner | | 1 | City Conway | | | | | ititude .080813° N | | | 92.436534 | | |
| R | Road/Street/Highway | У | | | | Section | Log Mi | | At Intersec | tion With | | 32.430004 | | |
| H | ARKRIDER ST | | | | | | | | BRUCEST | | | | | |
| N | lot in City, but | | | | | of the City | Limits | | | | | | | |
| N | ot at Intersection, b | | iles to two decin | nal places) | Direction | (N/S/E/W) | | Ci | ty | | | | | |
| | ot at intersection, t | | ce (feet or miles | to two decimal | olaces) | Direction (N/S/E/W) | - | елсе ра | int | | | | | |
| | | | And the state of | Electrical and | CF | RASH FACTORS | | | | | - Table 1 | | e section of the section | |
| | irst Harmful Event | 205 | Location Harmful | | 100 | School Bus Related | 000 | | dway Surface | 100 | , , , , , , | eather Con | | 25.00 |
| Non-Collision | 101 Fire/explosion 102 Immersion, full or pa | artial | 100 On road | | | 000 No, school bus not involved | | 100 E | Dry | | | 100 Clear | y. | 1 |
| lision | 103 Jackknife 104 Cargo/equipment los | | 102 Median 103 Roadsid | | | 100 Yes, school bus | | 102 \$ | Snow | | | 101 Cloudy | 108 Freezing | |
| | 113 Fell/jumped from mo | otor vehicle | 104 Gore | | | directly involved 101 Yes, school bus | | | ce or frost | | 1 | 102 Fog | freezing of | drizzle |
| | on or near motor veh | | | ng lane or zone | | indirectly involved Type of | 100 | 105 V | Nater (standing or movi Sand | ing) | _ | 103 Smog 104 Smoke | 110 Blowing | snow |
| Co | 198 Other non-collision 200 Pedestrian | | 108 Outside | way, location un right-of-way (tra | known fficway) | Intersection 000 Not an intersection | 100 | 107 M | Mud, dirt, or gravel | | | 105 Rain | 111 Severe c | |
| Collision | 201 Pedalcycle 202 Other non-motorist | | Type of C | | 202 | 100 Four-way intersection 101 T-intersection | | 198 C | | | | 106 Sleet | 112 Blowing s soil, or di | |
| | 203 Railway vehicle (train 204 Animal (live) | n, engine) | 100 Single v | ehicle crash | 202 | 102 Y-intersection | | 999 U | Inknown | | \dashv | 107 Hail 198 Other | | |
| with Non-Fixed | 205 Motor vehicle in trans | | 200 Front to 201 Front to | | | 103 L-intersection 104 Traffic circle | | _ | t Condition | 104 | | 190 Ollier | | |
| Fixed | 206 Parked motor vehicle 207 Falling/shifting cargo | or anything | | oe, same direction | | 105 Roundabout 106 Five-point or more | | 101 D | | | | 999 Unknown | | |
| Obje | set in motion by moto 208 Work zone/maintena | nce equipmen | t 205 Rear to s | | ction | 999 Unknown Road System | | 102 D 103 D | lusk lark - lighted | | | adway Cor | | |
| <u>C</u> | 298 Other non-fixed object 300 Impact attenuator/cra | | 206 Rear to r 980 Other (de | rear escribe below) | | 100 Interstate | 999 | | ark - not lighted ark - unknown lighting | | | 000 None | γ. | |
| Hisio | 301 Bridge overhead stru- 302 Bridge pier or suppor | icture | | | | 101 US highway 102 State highway | | 198 O | ther | | | | ue to prior crash | |
| n with | 303 Bridge rail | | Relation to | to | 101 | 103 County road 104 City street | | 999 U | nknown | | | 101 Backup du non-recur | ue to prior ring incident | |
| Fixed | 304 Cable barrier 305 Culvert | | 000 Non-juno 100 Intersecti | | | 105 Frontage road 106 Ramp | | Check | ironmental Facto | ers | | 102 Backup du congestion | | 1 |
| d Object | 306 Curb 307 Ditch | | 101 Intersecti 102 Entrance | | | 999 Unknown | | | 00 None 00 Weather conditions | | | 103 Toll booth | / plaza related | 1 |
| ect | 308 Embankment 309 Guardrail face | | 103 Entrance | or exit ramp rela grade crossing | ated | Property Classification | 100 | _ | 1 Visual obstructions | | | 104 Road surfa (wet, icy, s | ace condition snow, slush, etc.) | 1 |
| | 310 Guardrail end 311 Concrete traffic barrie | er | 105 Crossove | er related | | 100 Public property 101 Private property | | _ | 02 Glare | | _ | 105 Debris | | |
| | 312 Other traffic barrier 313 Tree (standing) | | 106 Driveway 107 Driveway | access related | | | | | 3 Animals in roadway 8 Other: | | | 106 Ruts, hole 107 Work zone | | |
| | 314 Utility pole/light support | ort | 109 Accelerat | ise path or trail tion or decelerati | on lane | | | | | | | | el-polished surface | 1 |
| | 316 Traffic signal support | | 110 Through 198 Other loc | roadway ation within an | | Trafficway Classific | ation | 99 | 9 Unknown | 100 | | 109 Obstructio 110 Traffic con | , | |
| | 317 Other post, pole, or su 318 Fence | ирроп | interchan | | (ahishe | 100 Trafficway, on road | | | | 100 | - | inoperative | e, missing, or obscur | |
| | 319 Mailbox 320 Building | | (,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | ondaidor, and ro | addidoj | 101 Trafficway, not on road 102 Non-trafficway (describe | e below) | | | | | 111 Shoulders 112 Non-highw | (none, low, soft, high | h) |
| + | 398 Other fixed object 999 Unknown | | 999 Unknown | | | | | | | | | 198 Other: | , | |
| - 1 | 98, 298, or 398, describe: | | | No. | | | | | | | | 999 Unknown | | |
| | | | | | WC | ORK ZONE CRAS | H INF | ORM | ATION | | | - Constitution | | |
| | | ocation R | | 970 | Work | Zone Type | | 970 | Worker(s) Prese | nt 970 | | | ment Present | 970 |
| 00 | Yes 16 | | first work zone | warning sign | 101 La | ne closure ne shift or crossover | | | 000 No 100 Yes | | 100 | Officer preser | | |
| ,53 | 10 | 02 Transition a | area | | 103 Int | ork on shoulder or median termittent or moving work | | | 970 Not applicable 999 Unknown | | 101 | | nent vehicle only pre | sent |
| | 10 | 03 Activity are 04 Termination | n area | | 198 Ot | her | | | | | | Unknown | | |
| | | 70 Not applica 99 Unknown | DIE | | 970 No | ot applicable | | | | | | | | |
| _ | | | | | 1000 U | DIDINAWII | | - 1 | | | 1 | | | |

| Crash Report # | 230322134 | | . 14 | | | | | | | Pa | ge ² of | 13 |
|---------------------|--|--|---|-----------|---------|--------------|---|-----------|---------------------|-------|--------------------|----|
| Photos Taken | | | | | A.Z. | | ATTACHMENTS | Albert S. | december 1975 | 161 | 75.54.15 | |
| Yes | | Тур | e | | | | | Des | cription | | | |
| ☑ No | Witness star | tement | | | Statem | ent fro | om Witness 1 | | | | | |
| | Witness stat | tement | | | Statem | ent fro | om Witness 2 | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | *************************************** | | | ************ | *************************************** | | | | | |
| | | | | | - | | | | | | | |
| | | | | | | | | **** | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | • | | | |
| 200 | | | | | | | | | | | | |
| 数中的分别与自由公 | THE RESERVE AND ADDRESS OF THE PERSON NAMED IN | THE RESIDENCE OF THE PARTY OF T | MATERIAL STATES | NON-V | EHICUL# | AR PR | OPERTY DAMAGE | a Section | - NEW TOTAL BERNELS | | ard and | |
| Description of Prop | erty Damage | Damage Estimate | Owne | | | Name | | Street | Address City | | State Postal Co | de |
| | | | | | | | | | | | 7 00101 00 | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | , , , , , , , , , , , , , , , , , , , | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| *** | | | | | | | | | | | | |
| Last Name | BU-1940434 | en de la companie | | WITNES | SES' CO | ONTA | CTINFORMATION | | PLONEN | | | |
| COOK | KARLA | First Name | | Middle Na | me S | Suffix | | | City | State | | de |
| | | | | KW | | | 5 WESTIN ESTATE | S DR | CONWAY | AR | 72034 | |
| RUICH | LANDO | ON | | BRYAN | | | 400 SAVANNAH PA | ARK CIR | CONWAY | AR | 72034 | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | - |
| | | | | | | | | | | | | |
| | | , | | | | | | | | | | |
| | _ | | | | | | | | | | | |
| | | | | | | | | | 1 | | | |

CRASH REPORT - ATTACHMENTS / PROPERTY DAMAGE / WITNESSES

ARKANSAS MOTOR VEHICLE CRASH REPORT

Page 3 of 13

| 1 | | | VE | HICLE IN | FORM | IATIC | N | Crash | Report # 230322134 | |
|---|---------------|---|---|--|----------------|-------------|------------|---|---|----------------|
| | | | DESC | RIPTION AN | D IDEN | TIFIC | ATION | Section 1 | | |
| Check if this vehicle had no driver | Hit and F | | | | | | 000 | Vehicle Body Type | e | 105 |
| | | I not leave the scene hicle & driver left the scene | | , vehicle & driver le | | Э | | Passenger Vehicles | | 100 |
| | | ly driver left the scene | 101 Yes | , only driver left the | scene | | | 100 2-door | | |
| VIN 1GTR2VE7X | DZ342688 | 3 | | | | | | 101 4-door 102 Hatchback | | |
| Vehicle Year, Mai | ce, and M | odel | | | | | | 103 Convertible | | |
| | GMC | | СКІ | R, V-series pick | un/Sierra | | | 104 Station wagon 105 Pick-up | | |
| | Make | | Model | rt, v-series pick | ирголента | | | 106 Mini-van | | |
| License Plate | | | | ☐ Mis | sing | | | | ats any number if personal; up to | 8 if business) |
| AR 356ZJA | A | | 2022 | | | all known | deteile\ | 108 Cargo van (10,000 l 109 Sport utility vehicle | IDS or less) | |
| State Number Trailer #1 License | Diate | | Year | | known (fill in | all known | details) | 110 Large utility vehicle | | |
| Trailer #1 Licelise | riale | | | ☐ Mis | sing | | | 111 Motor home/recreat 198 Other passenger ve | | |
| State Number | | | | ☐ Unk | known (fill in | all known | details) | Truck (> 10,000 lbs) | TIIOIG | |
| Trailer #2 License | Plate | | | | - | | | 200 Single unit truck (2 a | | |
| | | | | ☐ Mis | sing | | | 201 Single unit truck (3 d | or more axles) | |
| State Number | | | | Unk | nown (fill in | all known | details) | 202 Single unit truck with 203 Truck tractor only (b | | |
| _ | Same as o | driver Unknown | | | | | | 204 Tractor/semi-trailer | ob tany | |
| ALISON EVANS | | | | | | | | 205 Tractor/doubles | mana a suinmant | |
| Owner Address |] Same as o | friver Unknown | | | | | | 206 Construction/mainte 207 Farm equipment | nance equipment | |
| 1923 SIMMS ST | | | CONWAY | AR | . 7 | 72034-6 | 313 | 298 Other heavy vehicle | (GVWR/GCWR > 10,000 lbs) | |
| Street | | | City | State | e P | Postal Code | e | | more seats, including driver) | |
| Motor Carrier Type 000 Personal transporta | 1 ~ | Motor Carrier II | D Numbers | | | | | 300 School bus 301 Transit/city bus | | |
| 100 Interstate carrier | iuon | USDOT# | | | | | | 302 Motor coach/intercity | y/cross-country bus | |
| 101 Intrastate carrier | | MC/MX # | | | | | | 303 Limousine 304 Van (seats 9-15, incl | ludia a daia) | |
| 102 Not in commerce - g | | | | | | | | 390 Other vehicle (seats | 9-15, including driver) | |
| 999 Unknown | | State # | | | Stat | te | | 391 Other vehicle (seats | 16 or more, including driver) | |
| Motor Carrier Nam | e 🔲 U | Inknown | | | | | 1 | Cycle / Low Speed 400 Motorcycle | | |
| | | | | | | | | 401 Motor scooter | | |
| Motor Carrier Add | 1000 D II | - Independent | | *************************************** | | | | 402 Moped | | |
| Motor Carrier Addi | ess 🔲 0 | nknown | | | | | | 403 ATV (3, 4, or 6 whee 404 Snowmobile | is) | |
| | | | | | | | - 1 | 405 Golf cart | | |
| Street Cargo Body Type | | | City | State | P | ostal Code | | 406 Low speed vehicle 498 Other motorized cycl | le llevo en en el control | |
| 000 No cargo body | 104 Carg | o tank | 109 Dump | 100 046 | | | | Unknown | enow speed venicle | |
| 100 Bus | 105 Log | | 110 Concrete mixer | 198 Other | | | 1 | 999 Unknown type of mo | tor vehicle | |
| 101 Van / enclosed box 102 Grain / chips / grave | 106 Interr | nodal container chassis de towing another vehicle | 111 Auto transporter | | | | | If 198, 298, 390, 391, or 49 | | |
| 103 Pole trailer | 108 Flatb | ed | 112 Garbage / refuse | , | | | | | | |
| GVWR/GCWR | 970 | Hazardous Materials | s Placard 000 | Hazardous Ma | aterial ID | | | Hazare | dous Materials Released | |
| 100 10,000 lbs or less | | 000 Placard not required | 000 | (4-digit # or name fr of diamond or recta | rom middle | | | | /ehicle Cargo Compartme | 970 |
| 101 10,001 - 26,000 lbs 102 More than 26,000 lbs | | 100 Placard displayed 200 Placard required but r | and discussions of | Hazardous Ma | | 200 | | 000 No, | hazardous materials not release | |
| 970 Not applicable | 3 | 999 Unknown | iot displayed | (1-digit # from | | a33 | | 100 Yes | , hazardous materials released applicable (not carrying hazardo | us materials) |
| HAROLUM HAR | SURAN | CE SELECTION OF THE PERSON OF | | bottom of diamond) | | | | | applicable (not carrying hazardo | is materials) |
| Insurance | SUKAN | C LAND TO THE REAL PROPERTY. | Dames County | ************************************** | 20 (S) | | | AGE | | |
| ☐ Uninsured at time of | f crash | Unknown | Damage Severity 000 No damage | , | 102 | | | ontact Point heck 1) | Damaged Area | |
| | | (fill in any known details) | 100 Minor damage | | | _ | 7 8 | | (check all that ap | |
| nsurance Compan | У | | 101 Functional damag | | 1 | T | | 9 10 11 | 7 8 9 10 | 11 |
| SHELT | TER INSU | RANCE | 102 Disabling damage | е | | 6 | | 12 | | ☑ 12 |
| 1410.# | | | Damage Estimat | е | | | | | | |
| NAIC # | | | \$ | 10,000 | | 5 | 5 4 | 3 2 1 | 5 4 3 2 | 1 |
| | 23388 | | Damage Prior to | the Crash | | □ 0 | 00 Non-co | llision | ☐ 097 No damage | |
| Policy # | | | No prior damage | | | □ 1 | 00 Cargo I | loss | ☐ 113 Top | |
| Oncy # | | | Yes (describe be | elow) | | | 13 Top | | | |
| 03-1-0 | 010641708 | 3-0005 | | | | | 14 Underc | • | 114 Undercarriage | |
| | | | | | | □ 99 | 99 Unknov | vn | 999 Unknown | |
| | 41.4 | 9 8 /2 15 V 18 8 | ON THE | TOWI | NG | | | | | 100 |
| owed | 10 | | | | | | | | | |
| 00 Not towed 00 Towed, but not due to a | disabling dam | SMITH WRECKE | R SERVICE | | | | | | | |
| 01 Towed due to disabling | | Towed To | *************************************** | | | | | | | |
| | | 1570 E OAK ST | | | C | CONWA | Υ | AF | R 72032 | |
| | | Street | | | C | ity | | Sta | ate Postal Code | |
| | | | | | | | CI | RASH REPORT - MOTOR | VEHICLE DESCRIPTION AND IDE | NTIFICATION |

ARKANSAS MOTOR VEHICLE CRASH REPORT VEHICLE INFORMATION

| | | | 010 | 200 |
|----------------|-----------|---|-----|-----|
| | Page | 4 | of | 13 |
| Crash Report # | 230322134 | 4 | | |

| | | | М | OTOR VEHICLE | CIRCUMS | TANCES | | |
|--|----------------|--------------------------|---|--|-----------------------|---|-------------------------------------|---|
| Vehicle Usage | 000 | Emerger | ncy Vehicle L | | | Vehicle Maneuver | | NAME OF THE OWNER, OWNER, OWNER, OWNER, |
| 000 No special function | | 100 Non-er | mergency, non-tr | ransport | 100 | 100 Movement essentially | straight ahead | 100 |
| 100 Taxi | | 101 Non-er | nergency transp | ort | | 101 Negotiating a curve | su aight ahead | |
| 101 School bus/school transport 102 Church bus | | 102 Emerg | ency operation, | emergency warning equipme emergency warning equipme | ent not in use | 102 Backing | | |
| 103 Transit/commuter bus | | 970 Not ap | plicable | emergency warning equipme | ient in use | 103 Changing lanes 104 Overtaking/passing | | |
| 104 Intercity bus | | 999 Unknow | | | | 105 Turning right | | |
| 105 Charter/tour bus 106 Shuttle bus | | | | | | 106 Turning left | | |
| 107 Military | - 1 | Travel Di | | | 103 | 107 Making U-turn | | |
| 108 Police | | 100 Northb | | | | 108 Leaving traffic lane 109 Entering traffic lane | | |
| 109 Ambulance | | 101 Southb 102 Eastbo | | | | 110 Slowing | | |
| 110 Fire truck 111 Non-transport emergency service | 1 | 103 Westbo | | | | 111 Parked | | |
| 112 Incident response | | 104 Not on | | | | 112 Stopped in traffic 198 Other | | |
| 999 Unknown | | 999 Unknov | n | | | 130 Other | | |
| Vehicle Defects Check all that a | ipply. | | | | | 999 Unknown | | |
| ☑ 000 None | | | | | | | e Types and Statuses | |
| ☐ 100 Brake | ☐ 101 Exh | aust system | | □ 102 Padu days | | Check the box next to each | | |
| = | ☐ 104 Pow | | | ☐ 102 Body or doors ☐ 105 Suspension | | control device that was presi location of the crash. | ant at the 101 Functioning improp | |
| T | ☐ 107 Whe | | | 103 Suspension 108 Headlights | | Use the codes to the right to | record 102 Inoperative or miss | |
| - 400 T HH | ☐ 110 Turn | | | ☐ 111 Windows or windsh | iold | the status of each traffic condevice present. | 999 Unknown | |
| | ☐ 113 Wipe | • | | 114 Truck coupling, trail | | Traffic Cor | ntrol Device Type | Device Status |
| ☐ 115 Fuel system | ☐ 116 Cruis | se control | | hitch, or safety chai | | ☐ 000 None | k all that apply. | Use above codes. |
| ☐ 198 Other | | | | | | ☐ 100 Flashing traffic cont | tral signal | |
| | | | | | | 101 Traffic control signa | | |
| 999 Unknown | | | | | | ☐ 102 Stop sign | u | - |
| Trafficway Description | | 200 | Roadway S | urface | 1 404 | 102 Step sign | | - |
| 100 One-way trafficway 200 Two-way, not divided | | 200 | 100 Concrete | | 101 | 104 Slow or warning sig | n | - |
| 201 Two-way, not divided, with a conti | nuous left tur | rn lane | 101 Asphalt 102 Gravel | | | ☐ 105 Person (officer, flag | | |
| 300 Two-way, divided, unprotected (pa 400 Two-way, divided, positive cable b | ainted >4 feet | t) median | 103 Dirt 198 Other | | | ☐ 106 School zone sign/de | | |
| 401 Two-way, divided, positive concret 498 Two-way, divided, other type of po | te barrier | | 150 Other | | | ☐ 107 Pedestrian signal | | |
| 1430 Two-way, divided, other type of po | sitive parrier | | 999 Unknown | | | ☐ 108 No passing signal | | |
| 999 Unknown | | | | | | ☐ 109 Words or symbols p | ainted on roadway | |
| Roadway Grade 100 Level 999 Unknown | | 100 | Roadway Al | lignment | 100 | ✓ 110 Traffic lanes marked | | 100 |
| 101 Hillcrest | | | 100 Straight 200 Curve left | | | ☐ 111 Railway crossing will | th gate and signals | |
| 102 Uphill 103 Downhill | | | 201 Curve right | | | ☐ 112 Railway crossing will | th flashing signals only | |
| 104 Sag (bottom) | | | 299 Curve, dire 999 Unknown | ction unknown | | ☐ 113 Railway crossing wit | | |
| Total # of Lanes | | | Posted Spee | ed Limit | | ☐ 198 Other: | | |
| | | 6 | Use the posted sp to this vehicle at t | peed limit that applied the time of the crash. | 45 | 999 Unknown | | |
| | 湖岸区 | IT IS | DOM: NO | MOTOR VEHICL | LE EVENT | S | 2.1 20.1 在Marks | AND THE REAL PROPERTY. |
| Sequence of Events 1 205 | 2 | | 3 | 4 5 | 6 | 7 | 8 9 | 10 |
| Most Harmful Event 205 | i i | | | | | | | |
| | | | | | | | | |
| Non-Collision 100 Overturn/rollover | | | | Fixed Object | Collisio | on with Fixed Object | | Unknown |
| 101 Fire/explosion | | 200 Peda 201 Peda | | | | ct attenuator/crash cushion | 318 Fence | 999 Unknown |
| 102 Immersion, full or partial | | 202 Othe | r non-motorist | | | e overhead structure e pier or support | 319 Mailbox 320 Building | |
| 103 Jackknife | | 203 Raily | vay vehicle (train | n, engine) | 303 Bridg | | 398 Other fixed object | |
| 104 Cargo/equipment loss or shift 105 Equipment failure | | 204 Anim | al (live) r vehicle in trans | | 304 Cable | | | |
| (blown tire, brake failure, etc.) | | | ed motor vehicle | | 305 Culve 306 Curb | | If 198, 298, or 398 is used, descri | ribe below: |
| 106 Separation of units | | 207 Fallin | g/shifting cargo | or | 307 Ditch | | | |
| 107 Ran off roadway right 108 Ran off roadway left | | anyth | ning set in motion | n by motor vehicle | 308 Emba | | | |
| 109 Deliberately crossed median | | 208 Work | zone/maintenar non-fixed object | nce equipment | 309 Guar | | | |
| 110 Unintentionally crossed median | | | avec onlec | | 310 Guar 311 Conc | drail end rete traffic barrier | | |
| 111 Crossed centerline | | | | | | traffic barrier | | |
| 112 Downhill runaway 113 Fell/jumped from motor vehicle | | | | | 313 Tree | (standing) | | |
| 114 Reentering roadway | | | | | 314 Utility | pole/light support c sign support | | |
| 115 Object thrown or fallen on or near m | otor vehicle | | | | 316 Traffi | c sign support c signal support | | |
| 98 Other non-collision | | | | | | post, pole, or support | | |
| | | | | | | CDASH DED | ORT MOTOR VEHICLE CIRCLINATE | 11050 1110 |

102 Windshield

103 Back window 104 Back door/tailgate opening 105 Roof opening (sun roof, convertible top down) 106 Roof (convertible top up) 198 Other (e.g., back of pickup truck,

torn-off roof, car cut in half)

CRASH REPORT - DRIVER INFORMATION

4D

5D

##D

5A

5B

##B

5C

##C

Aisle

4E

5E

##E

4F

5F

999 Unknown

CRASH REPORT - DRIVER CONDITION AND CIRCUMSTANCES

☑ 502 Inattentive, careless, negligent, or erratic operation

☐ 500 Reckless operation

☐ 501 Aggressive operation

☐ 503 Under the influence of alcohol ☐ 504 Under the influence of drugs

204 Swerved or avoided due to object in roadway

205 Swerved or avoided due to animal in roadway

ARKANSAS MOTOR VEHICLE CRASH REPORT VEHICLE INFORMATION

| | | 010 | 200 |
|------|---|-----|-----|
| Page | 7 | of | 13 |
| | | | |

| 31/4 | | | The second secon | PIRTION AND IDE | | | orașii Keport # | 230322134 | |
|--|---------------|--|--|--|---------------------|--|---|--|-------------|
| Check if this vehicle | Hit and R | un | DESC | RIPTION AND IDE | | 14 41 4 6 | de Tura | | |
| had no driver | | not leave the scene | 100 Yes | s, vehicle & driver left the sce | | 00 Vehicle Bo | | | 101 |
| | | icle & driver left the scen driver left the scene | e 101 Yes | s, only driver left the scene | | 100 2-door | 31110100 | | |
| VIN 2C3CDXAG3 | | | | | | 101 4-door | -1- | | |
| Vehicle Year, Mak | | | | | | 102 Hatchbad 103 Convertib | | | |
| | Dodge | del | Ohaan | | | 104 Station w | ragon | | |
| | Jouge Make | | Charg Model | ger | | 105 Pick-up 106 Mini-van | | | |
| License Plate | | | Woder | Missing | | 107 Passenge | er van (seats any num | ber if personal; up to 8 if | f business) |
| AR 568VU | Y | | | _ , | | 108 Cargo vai | n (10,000 lbs or less) | | , |
| State Number Trailer #1 License | Plate | | Year | ☑ Unknown (fill | n all known detail | 110 Large utili | ity vehicle | | |
| Trailer # 1 Electrise | riate | | | ■ Missing | | | me/recreational vehicle ssenger vehicle | • | |
| State Number | | | | Unknown (fill i | n all known detail: | | | | |
| Trailer #2 License | Plate | | | Missing | | | it truck (2 axles) | | |
| | | | | | | 202 Cingle | t truck (3 or more axle t truck with trailer | s) | |
| State Number Owner Name | Same as dr | iver 🗖 Helesee | | Unknown (fill i | n all known details | 203 Truck trac | tor only (bobtail) | | |
| FAULKNER COUN | _ | | | | | 204 Tractor/se 205 Tractor/do | | | |
| Owner Address | | | | | | | ion/maintenance equip | oment | |
| 801 LOCUST AVE | _ came as ur | iver Unknown | COMMAN | | | 207 Farm equi | pment | | |
| Street | | | CONWAY | AR | 72034-5330 | | vy vehicle (GVWR/GC mo (9 or more seats, | | |
| Motor Carrier Type | 00 | 00 Motor Carrier | | State | Postal Code | 300 School bus | S | <u> </u> | |
| 000 Personal transportal 100 Interstate carrier | tion | USDOT # | | | | 301 Transit/city | y bus ch/intercity/cross-coun | try bus | |
| 101 Intrastate carrier | | MC/MX# | | | | 303 Limousine | | | 9 |
| 102 Not in commerce - g | overnment | INO/INIX # | | | | 304 Van (seats | 9-15, including driver |) | |
| 103 Not in commerce - o 999 Unknown | iner truck | State # | | Sta | ite | 391 Other vehi | cle (seats 9-15, includ cle (seats 16 or more, | ing ariver) including driver) | 100 |
| Motor Carrier Name | e 🔲 Un | known | | | | Cycle / Low S | peed | 3 , | |
| | | | | | | 400 Motorcycle 401 Motor scoo | | | |
| Motor Comics Add | 🗖 🗠 | | | | | 402 Moped | | | |
| Motor Carrier Addr | ess 🔲 Un | Known | | | | 403 ATV (3, 4, 404 Snowmobil | | | |
| | | | | | | 405 Golf cart | | | |
| Street Cargo Body Type | | | City | State | Postal Code | 406 Low speed | vehicle prized cycle/low speed | histo | |
| 000 No cargo body | 104 Cargo | tank | 109 Dump | 198 Other | 000 | Unknown | mzed cyclenow speed | venicie | |
| 00 Bus 01 Van / enclosed box | 105 Log | | 110 Concrete mixer | | | | ype of motor vehicle | | |
| 02 Grain / chips / gravel | 100 Interm | odal container chassis e towing another vehicle | 111 Auto transporter | 999 Unknown | | If 198, 298, 390, | 391, or 498, describe b | elow: | |
| 03 Pole trailer | 108 Flatbe | d | · · · · · · · · · · · · · · · · · · · | • | | | | | |
| GVWR/GCWR | | Hazardous Material | s Placard 000 | Hazardous Material II |) | | Hazardous Mate | erials Released | 970 |
| 00 10,000 lbs or less 01 10,001 - 26,000 lbs | | 000 Placard not required 000 Placard displayed | | (4-digit # or name from middle of diamond or rectangular box) | | | from Vehicle Ca | rgo Compartment | 370 |
| 02 More than 26,000 lbs | 2 | 200 Placard required but | not displayed | Hazardous Material C | lass | | 100 Yes, hazardous n | naterials not released materials released | |
| 70 Not applicable | 9 | 999 Unknown | | (1-digit # from bottom of diamond) | | | | not carrying hazardous m | naterials) |
| | SURANC | E | | 2. 10万字公子 设有 | D | AMAGE | ta Lang | (visit set set vice) con | |
| nsurance | | Unknown | Damage Severity | 102 | | al Contact Poin | t | Damaged Areas | |
| Uninsured at time of | | (fill in any known details) | 000 No damage 100 Minor damage | | | (check 1) | (c | heck all that apply | 0 |
| nsurance Company | , | | 101 Functional dama | ge | | | 11 7 | 8 9 10 1 | 11 |
| ASSOCIATION OF A | ARKANSA | S COUNTIES RISK | 102 Disabling damage | e | | | | | <u> </u> |
| | NAGEMEN | NT | Damage Estimat | e | 1 | | | | 12 |
| IAIC# | | | \$ | 12,000 | | | 1 5 | | 7 |
| | | | Damage Prior to | the Crash | □ 000 No | n-collision | | 7 No damage | _ |
| al: # | | | ✓ No prior damage | | ☐ 100 Ca | | | | 1 |
| olicy # | | | Yes (describe be | elow) | ☐ 113 Top | | 113 | | |
| F | RMF-1035 | | | | ☐ 114 Un | | | 1 Undercarriage | |
| | | | | | ☐ 999 Uni | known | 999 | Unknown | |
| awad | | The second second | | TOWING | | | | | |
| owed 0 Not towed | 101 | Towed By | | | | | | | |
| 0 Towed, but not due to di | sabling dama | PRO AUTO | | | | | | | |
| 1 Towed due to disabling of | damage | Towed To | BD | | | The second secon | | | |
| | | #6 RANCHETTE | KU | • | CONWAY | | AR | 72032 | |
| | | Street | | | City | CRASH REPORT | State F | Postal Code SCRIPTION AND IDENTIF | EICATION |
| | | | | Daga 12 of 2 | ^ | STOTOL INCHORT | MOTOR VEHICLE DE | SORIF HON AND IDENTIF | TOATION |

ARKANSAS MOTOR VEHICLE CRASH REPORT VEHICLE INFORMATION

| | | 010 | 200 |
|------|---|-----|-----|
| Page | 8 | of | 13 |

| 2 | | | | VEHICLE | INFOR | MAT | ION | Crash Report # | 230322134 | |
|--|-------------------|--|---|--|-------------------------------|--------------------------|--|--|----------------|------------------|
| | | | | MOTOR VEHIC | | | | | | |
| Vehicle Usage | 108 | Emerge | ncy Vehicle | | | 103 | Vehicle Maneuver | | | 100 |
| 000 No special function 100 Taxi 101 School bus/school transport 102 Church bus 103 Transit/commuter bus 104 Intercity bus 105 Charter/tour bus | | 101 Non-ei 102 Emerg | ency operation, plicable | | quipment not quipment in u | in use | 100 Movement essentially 101 Negotiating a curve 102 Backing 103 Changing lanes 104 Overtaking/passing 105 Turning right 106 Turning left | straight ahead | | 100 |
| 106 Shuttle bus 107 Military 108 Police 109 Ambulance 110 Fire truck | | 100 Northb | vel Direction Northbound Southbound Fastbound | | | 101 | 107 Making U-turn 108 Leaving traffic lane 109 Entering traffic lane 110 Slowing | | | |
| 111 Non-transport emergency servi 112 Incident response 999 Unknown Vehicle Defects Check all that | | 103 Westbo 104 Not on 999 Unknow | roadway | | | | 111 Parked 112 Stopped in traffic 198 Other | | | |
| ✓ 000 None | арргу. | | | | | | 999 Unknown | | | |
| ☐ 100 Brake ☐ 103 Steering ☐ 106 Tires ☐ 109 Tail lights ☐ 112 Mirrors | ☐ 104 Pc | heels rn signals | 1 | ☐ 102 Body or doors ☐ 105 Suspension ☐ 108 Headlights ☐ 111 Windows or w | vindshield | | Traffic Control Device Types and Statuses Check the box next to each traffic control device that was present at the location of the crash. Use the codes to the right to record the status of each traffic control device present. 100 Functioning properly 101 Functioning improperly 102 Inoperative or missing 999 Unknown | | í | |
| 115 Fuel system | ☐ 113 Wi | pers uise control | | 114 Truck coupling | | | Traffic Col | ntrol Device Type k all that apply. | | Use above codes. |
| ☐ 198 Other | | and control | | This i, or salet | y Chama | | 000 None | | | |
| 196 Other | | | | | | | 100 Flashing traffic con | | | |
| 999 Unknown | | | | | | | 101 Traffic control signa | ıl | | |
| Trafficway Description | | | | | | | 102 Stop sign | | | |
| 100 One-way trafficway | | 200 | Roadway 5 | Surface | | 101 | 103 Yield sign | | | |
| 200 Two-way, not divided 201 Two-way, not divided, with a cor | diamenta laft t | | 101 Asphalt | | | | 104 Slow or warning sig | | | |
| 300 Two-way, divided, unprotected (| painted >4 fe | et) median | 102 Gravel 103 Dirt | | | | 105 Person (officer, flag | man, crossing guard) | | |
| 400 Two-way, divided, positive cable 401 Two-way, divided, positive concr | barrier | | 198 Other | | | | ☐ 106 School zone sign/de | evice | | |
| 498 Two-way, divided, other type of p | ositive barri | er | 999 Unknown | | | | ☐ 107 Pedestrian signal | | | |
| 000 | | | - | | | ☐ 108 No passing signal | | | | |
| 999 Unknown Roadway Grade | | 1 | | | | | 109 Words or symbols painted on roadway | | | |
| 100 Level 999 Unknown | | 100 | Roadway Alignment 100 100 Straight | | | 100 | ☑ 110 Traffic lanes marked 100 | | | 100 |
| 101 Hillcrest 102 Uphill | | | 200 Curve left | | | | ☐ 111 Railway crossing with gate and signals | | | |
| 103 Downhill | | | | ction unknown | | | ☐ 112 Railway crossing with flashing signals only | | | |
| 104 Sag (bottom) | | | 999 Unknown | | | - | ☐ 113 Railway crossing will | th crossbuck only | | |
| Total # of Lanes | | 6 | Posted Spe | | | 45 | ☐ 198 Other: | | | |
| A COMPANY OF THE PARTY OF THE P | ACCULATION OF | | to this vehicle at | speed limit that applied the time of the crash. | | 1 | 999 Unknown | Lagrange data and | Control on the | 500 |
| | | | | MOTOR VEH | HICLE E | VENT | S | 交更各位区域 。 | | W. 24. |
| Sequence of Events 1 20 Most Harmful Event 20 | ∹ ' | | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| Non-Collision | | Collisia | on with Non | -Fixed Object | | | | | | |
| 00 Overturn/rollover | | 200 Pede | estrian | -rixed Object | | | on with Fixed Object ct attenuator/crash cushion | 318 Fence | | Inknown |
| 01 Fire/explosion 02 Immersion, full or partial | | 201 Peda | alcycle r non-motorist | | 3 | 01 Bridg | e overhead structure | 319 Mailbox | 3: | 99 Unknown |
| 03 Jackknife | | 203 Raily | vay vehicle (trai | n, engine) | | 02 Bridg 03 Bridg | e pier or support e rail | 320 Building 398 Other fixed object | | |
| 04 Cargo/equipment loss or shift 05 Equipment failure | | 204 Anim | al (live) r vehicle in tran | | 3 | 04 Cable | barrier | , | | |
| (blown tire, brake failure, etc.) | ed motor vehicle | е | | 05 Culve 06 Curb | n | If 198, 298, or 398 is t | used, describe | e below: | | |
| 06 Separation of units 07 Ran off roadway right | ng/shifting cargo | or on by motor vehicle | | 07 Ditch | | | | 1 | | |
| 08 Ran off roadway left | zone/maintena | nce equipment | | 08 Emba 09 Guard | drail face | | | | | |
| 09 Deliberately crossed median 10 Unintentionally crossed median | r non-fixed obje | ct | | 10 Guard | | | | | | |
| 11 Crossed centerline | | | | | | | rete traffic barrier traffic barrier | | | |
| 12 Downhill runaway 13 Fell/jumped from motor vehicle | | | | | 3 | 13 Tree | (standing) | | | |
| 14 Reentering roadway | | | | | | | pole/light support | | | |
| 15 Object thrown or fallen on or near 98 Other non-collision | motor vehicle | е | | | 3 | 16 Traffic | signal support | | | |
| | | | | | 3 | 17 Other | post, pole, or support | | | |
| | | | | Danie | 14 of | 20 | CRASH REPO | ORT - MOTOR VEHICLE | CIRCUMSTAN | CES AND EVENTS |

ARKANSAS MOTOR VEHICLE CRASH REPORT

| 200 | 010 | | |
|-----|-----|---|------|
| 13 | of | 9 | Page |
| | | | |

| 1 " | 2 | more # | | | , | W | NIOAC | | K VEHICLE CKA | | PURI | | | rage 9 | 01 13 |
|--------------------|------------------------|-------------|-----------|-----------------|------------------------------|------------------------|----------------------|------------------------------------|--|-------------|----------------------------|--------------|-------------------------|--------------------------------------|-----------------|
| | | | | | | | - | DRIVE | R INFORMATION | V | | Crash | Report # | 230322134 | |
| | | | S V | | | | | DRIV | ER INFORMATION | ozalita: | 1 23 | A. T. | 9 | | |
| Name | | Unknow | 'n | | | | | | | Date of B | irth/Age | Sex V | Male | Race | 100 |
| MAHE | R | | | C | CODY | | | JAMES | | 08/18/ | | _ |] Female | 100 White/Caucasia | |
| Last | | | | F | irst | | | Middle | Suffix | Age | | |] Unknow | | American |
| Addre | ss 🗌 | Unknow | 'n | | | | | | Odnix | | | | | 102 Hispanic 103 Asian/Pacific Is | landor |
| 3 HIDI | DEN OA | K DR | | | | | | VILONIA | | AR | 7217 | 3 | | 104 American India | |
| Street | | | | | - make a consistence | Annual management | | City | | State | Postal | | | 198 Other 999 Unknown | |
| e-derepot m. | | | | | | | etrials are D | THE RESERVE OF THE PERSON NAMED IN | CENSE INFORMATI | | rustai | Cone | | 1999 OUKUOWII | |
| Licens | se Status | s 10 | 00 L | icense N | lumber | | | | Restrictions on Licens | | all that apply. | Restr | ictions V | iolated | |
| | licensed id license | | | | 5 | 9223114 | 192 | | ☑ 000 None | Oneck a | и илас арргу. | | | Check | all that apply. |
| 200 Sus | | | L | icense S | itate | Ti i | cense Cla | 100 | | | | ☑ 000 | None | | |
| 201 Rev | | | | | AR | - | | | ☐ 100 With licensed adult | | | □ 100 | With licens | ed adult | |
| 202 Exp 203 Can | irea icelled or a | lenied | | | | | |) | ☐ 101 Corrective lenses | | | 101 | Corrective | lenses | |
| 204 Disc | qualified | | | ☐ Yes | ercial Driv | | nse? | | ☐ 102 Mechanical aid | | | 1 02 | Mechanica | laid | |
| 999 Unk | | | | | <u> </u> | | | | ☐ 103 Prosthetic aid | | | □ 103 | Prosthetic | aid | |
| Check all | sements that apply. | on Lice | ense | | Check all th | ements at apply. | Violated | | ☐ 104 Automatic transmission | on | | □ 104 | Automatic | transmission | |
| 2 000 | None | | | | ☑ 000 No | one | | | ☐ 105 Outside mirror | | | | | | |
| □ 100 | Double/trip | le trailers | | | ☐ 100 Do | | o trailore | | | | | | Outside mi | | |
| _ | Passenger | | | | - | - | e trailers | | 106 Daylight only | | | | Daylight on | | |
| | | | | | ☐ 101 Pa | | | | ☐ 107 Class B or C with pas | sengers and | class D | 107 | Class B or | C with passengers and | class D |
| | Tank vehic | | | | 102 Ta | nk vehicl | 9 | | ☐ 108 Class C only with pas | sengers | ~ | 108 | Class C on | y with passengers | |
| | Hazardous | | | | ☐ 103 Ha | zardous | materials | | ☐ 109 Vehicles without airbr | akes | | 109 | Vehicles wi | thout airbrakes | |
| 104 | Tank vehic | le & hazar | dous m | aterials | ☐ 104 Ta | nk vehicle | & hazardo | us materials | ☐ 110 Interlock device | | | 110 | Interlock de | vice | |
| 105 8 | School | | | | ☐ 105 Sci | hool | | | 111 School, church, or tra | nsit bus | | □ 111 | School, chu | rch, or transit bus | |
| ☐ 106 N | Motorcycle | | | | ☐ 106 Mo | torcycle | | | ☐ 112 Class D only with pas | sengers | | _ | | y with passengers | |
| ☐ 107 N | Aotor drive | n cycle | | | ☐ 107 Mo | tor driver | cycle | | ☐ 113 Diesel fuel, fertilizer o | | | | | fertilizer only | |
| □ 108 V | /alid withou | ut photo | | | ☐ 108 Val | id withou | t photo | | ☐ 114 Seasonal farm service | | | | | rm service vehicle | |
| ☐ 198 C | Other (desc | ribe below | v) | | ☐ 198 Oth | er (descr | ibe below) | | ☐ 198 Other (describe below | 1) | | | Other (desc | | |
| | | | | | | | | | | , | | | - 101 (0000 | nibe balon, | |
| | | | | | | | | | | | | | | | |
| | | | | - 1 | | | | | | | | | | | |
| 三 沙兰·1 | | 200 | necess. | 45-5-6 | attacker | 0.25 | | - | | | | | - | | |
| Seating | Positio | n | 1. 1. 1. | Jan Class | and the same | U | | | AND SAFETY INFO | RMATION | VIEW C | | | | |
| | | " | | | | | 110 | 1 | Systems Used | | | 100 | _ | cle Helmet Usage | 000 |
| Standa | ard Vehi | cle Seat | s | Other | Seating F | osition | 18 | 100 Shoulde | ed - motor vehicle occupant r and lap belt used | | | | 000 No hel 100 DOT-c | | |
| | Fro | | | 800 Slee | eper section | | | 101 Shoulde | r belt only used | | | | motoro | ycle helmet wom | |
| Row L | eft Midd | le Right | Other | 801 Pas | ssenger sect closed passe | ion of bu | 3 | 102 Lap belt 103 Restrain | only used t used - type unknown | | | | | OT-compliant ycle helmet wom | 1 |
| 1 1 | 110 120 | 130 | 180 | 803 Une | enclosed passe | inger/car ssenger/c | go area argo area | 104 Child res | straint system - forward facing | | | | 102 Helmei | | |
| 2 2 | 210 220 | 230 | 280 | 804 Pas | ssenger/carg | o area, | ango unou | 105 Child res | straint system - rear facing | | | | | vn if DOT-compliant | |
| 3 3 | 10 320 | 330 | 380 | unk 805 Trai | nown if encl | osed | | | straint - type unknown | | | | | wn if helmet worn ection Usage | |
| 4 4 | 10 420 | 430 | 480 | | ing on motor | vehicle e | exterior | 198 Other | | | | | Yes | ection usage | |
| _ | _ | _ | | Unkno | | | | 970 Not appli | icable | | | | ☑ No | | |
| 5 5 | 520 | 530 | 580 | 999 Unk | | | | 999 Unknowr | | | | | Unkno | wn | |
| 7 | | | | | | | | Air Bags [| Deployed | | Ejection | | 000 | Extrication | 000 |
| Bus Sea | ting Pos | ition | | | | | | Check all tha | t apply: | | 000 Not eje | | | 000 Not extricated | 000 |
| (Complete | if 801 was | selected fo | or Seatin | g Position a | above.) | | | ☐ 000 Not | deployed | | 100 Ejected | | | 100 Extricated | |
| | | | | Front | | | | ☑ 100 Dep | | | 970 Not ap | | | 999 Unknown | |
| | Driver | | | | | | | ☑ 101 Dep | | | 999 Unknow | wn | | | |
| 1A | 1B | 1C | 4 | | 1D | 1E | 1F | | loyed: curtain | | Ejection | | | | 000 |
| 2A 3A | 2B 3B | 2C 3C | 1 | | 2D | 2E | 2F | ☐ 198 Dep | noyed: other | | 000 Not eje 100 Side do | | | 970 Not applicable 999 Unknown | |
| 4A | 4B | 4C | 1 | | 3D 4D | 3E | 3F 4F | ☐ 970 Not | applicable | | 101 Side wi | indow | 'y | 303 OHKHOWH | |
| 5A | 5B | 5C | 1 | Aisle | 5D | 4E 5E | 5F | 999 Unk | | | 102 Windsh | | | | |
| | | | 1 | S e | 30 | JE | 56 | | | | 103 Back w 104 Back de | | ate opening | | |
| | | | | | . | | . | | | | 105 Roof of | pening (s | sun roof, | | |
| : | : | : | | | : | : | : | | | | conver 106 Roof (c | tible top | | | |
| | | | | | | | | | | | 198 Other (| e.g., bac | k of pickup | | |
| ##A | ##B | ##C | | | ##D | ##E | ##F | | | | torn-of | f roof, ca | r cut in half |) | |
| - | | | | | | | | | | | | | CRASH | REPORT - DRIVER INF | ORMATION |

ARKANSAS MOTOR VEHICLE CRASH REPORT

| | | 010 | |
|-----|----|-----|----|
| age | 10 | of | 13 |

DRIVER INFORMATION Crash Report # 230322134 MEDICAL INFORMATION Injury Status Type of Medical Transportation 101 **EMS Notified EMS Arrived** 1 (K) Fatal injury 000 Not transported 03/05/2022 03/05/2022 10:13 PM 2 (A) Suspected serious injury 100 EMS air Date Time 3 (B) Suspected minor injury 101 EMS ground Transported to Medical Facility By 4 (C) Possible injury 102 Law enforcement 5 (O) No apparent injury Pafford - CONWAY 198 Other Trauma Band # Medical Facility Transported To B984049 199 Transported, but method unknown UAMS Medical Center, Little Rock, AR 999 Unknown if transported **DRIVER CONDITION AND CIRCUMSTANCES** Condition at Time of Crash **Driver Distracted By** 000 **Driver Vision Obscured By** 000 000 Not distracted ☑ 000 Apparently normal 000 No obstruction noted 106 Not in-transport motor vehicle 100 Manually operating an electronic 100 Rain, snow, fog, smoke, sand, or dust (parked, working) ☐ 100 Physically impaired communication device (texting, typing, dialing) 101 Reflected glare, bright sunlight, 107 Splash or spray of passing vehicle 101 Emotional (depressed, angry, disturbed, etc.) 101 Talking on hands-free electronic device or headlights 108 Inadequate defrost or defog system 102 III (sick) or fainted 102 Talking on hand-held electronic device 102 Curve, hill, or other roadway 109 Inadequate vehicle lighting system 103 Other activity with an electronic device ☐ 103 Asleep or fatigued design feature 110 Obstruction interior to the vehicle 104 Passenger ☐ 104 Under the influence of medication or drugs 103 Building, billboard, or other structure 111 External mirrors 980 Other distraction inside the vehicle 104 Trees, crops, or vegetation 112 Broken or improperly cleaned windshield 105 Under the influence of alcohol 981 Other distraction outside the vehicle 105 In-transport motor vehicle 113 Obstructing angles on vehicle ☐ 198 Other 999 Unknown if distracted (including load) 199 Vision obscured - no details If 980 or 981, describe below: 980 Other visual obstruction (describe below) 999 Unknown **Driver Suspected** Alcohol Test Type Given Alcohol Test Result Status 000 Blood Alcohol Content | Speeding Related 000 of Alcohol Usage 000 No test given 100 Results pending 000 Not speeding 001 Test refused 101 Results received 100 Racing ☐ Yes 100 Blood test 970 Not applicable 101 Exceeded speed limit 101 Breath test 999 Unknown 102 Too fast for conditions ✓ No 102 Urine test 999 Unknown 198 Other type of test ☐ Unknown Result received from 999 Unknown if tested **Driver Suspected Drug Test Type Given Drug Test Results** 000 Result received from Crime Lab Citations of Drug Usage 000 No test given Pending/Negative Not Applicable/Unknown Citation # Charges 001 Test refused 000 Results negative 970 Not applicable ☐ Yes 100 Blood test ☐ 100 Results pending 999 Unknown 101 Urine test **☑** No 102 Both blood and urine tests Positive Results (check all that apply) 198 Other type of test 200 Amphetamines ☐ Unknown ☐ 206 Methamphetamines 201 Barbiturates ☐ 207 Opiates 999 Unknown if tested ☐ 202 Benzodiazenines 208 Oxycodone 203 Cannabinoids 209 Propoxyphene 204 Cocaine 210 Phencyclidine (PCP) ☐ 205 Methadone 298 Other positive result (describe below) DRIVER ACTIONS AT TIME OF CRASH Check all that apply: ☑ 000 No contributing action 999 Unknown Disregarded Traffic Signs or Controls Improper Maneuver Other Actions ☐ 100 Disregarded red light 300 Improper right turn ☐ 600 Impeding traffic ☐ 101 Disregarded other traffic signal ☐ 301 Improper left turn 601 Ran off roadway ☐ 102 Disregarded stop sign 302 Improper U-turn 602 Crowded off roadway ☐ 103 Disregarded yield sign ☐ 303 Improper backing 603 Crossing median ■ 104 Disregarded other traffic sign 304 Improper passing 604 Failed to yield right-of-way ☐ 105 Disregarded other road markings ☐ 305 Improper lane change 605 Failed to keep in proper lane ■ 106 Disregarded officer or flagman 306 Improperly parked ☐ 606 Wrong side of road Swerved or Avoided ☐ 607 Wrong way Improper Use of Lights or Signals 200 Swerved or avoided due to wind ☐ 608 Followed too closely ☐ 400 Driving without lights 201 Swerved or avoided due to slippery surface ☐ 609 Cutting in 401 Failed to dim headlights 202 Swerved or avoided due to motor vehicle ☐ 610 Over-correcting or over-steering ☐ 402 Failed to or improper signal ☐ 203 Swerved or avoided due to non-motorist in roadway ☐ 980 Other contributing action (describe below) Unsafe Operation 204 Swerved or avoided due to object in roadway ☐ 500 Reckless operation 205 Swerved or avoided due to animal in roadway ☐ 501 Aggressive operation 502 Inattentive, careless, negligent, or erratic operation ☐ 503 Under the influence of alcohol ☐ 504 Under the influence of drugs

CRASH REPORT - DRIVER CONDITION AND CIRCUMSTANCES

Total # of Passengers

ARKANSAS MOTOR VEHICLE CRASH REPORT

| | | 313 | 233 |
|------|----|------|-----|
| Page | 11 | of [| 13 |
| | | | |

PASSENGER INFORMATION
Complete this sheet for passengers in each motor vehicle.

Crash Report # 230322134


| | | | | | P/ | ASSENGE | R INFORMATIO | N | | | | | |
|---|-----------|------------------------------|--------------------|---|------------|------------------------------|---|-------------------|-----------|--|------------------------------|-------------|-------------|
| MOTOR VEHIC | CLE# | 1 | | | | | | | | | PASSE | IGER # | 1 |
| Name | | | | | | | | Date of Birth/Ag | e Sex F | Male | | as Depl | _ |
| BUNKER | | | JAM | ES | GF | REGORY | | 03/01/1982 | | Female | , | that apply: | 3 |
| Last | | | First | | Mid | dle | Suffix | Age: 40 | | Unknown | T 000 | Not deplo | |
| Address | | | | | | | | | Race | | | Deployed | : front |
| 220 BETTY ST | | | | | BLENWO | DOD | AR | 71943 | | 100 | | Deployed | |
| Injury Status | 10 | D- | -141 | | ity | | State | Postal Code | | | | Deployed | |
| 4 | 3 | eating Po | | Ejection | Ejecti | on Path | Extrication | Restraint System | Helme | t Used | | Deployed | |
| Type of | EMS | Notified |) | 000 | | 000 | 000 | 100 | | 000 | | Not applie | |
| Medical | | 5/2022 | | 10:12 PM | | | ed To Medical Facili | ity By | Eye Pr | otection | - | Unknown | |
| Transportation | 1 | MM/DD/YYYY | | | | Pafford - C | UNWAY | | | 000 | If 198 is cl | necked, de | scribe belo |
| 101 | | Arrived |) | Time (HH:MM AM/PM) | | Madical Es | acility Transported | | _ | a Band # | 1 | | |
| | 03/05 | 5/2022 | | 10:18 PM | | | egional Health System | | B98414 | 46 | | | |
| | Date (N | MM/DD/YYYY |) | Time (HH:MM AM/PM) | | Conway IN | sgional mealth System | n, Conway, AR | | | | | |
| MOTOR VEHIC | | | S SHIP | THE RESERVE TO SHARE THE PARTY OF THE PARTY | W. J. 4 | 10 12 Sec. 19 | | | | | DACCEN | CED # | |
| Name | | | | | | | | Date of Birth/Age | Sex [| Control of the latest and the latest | Air Bag | | rad . |
| | | | | | | | | Date of Birthings | | Female | Check all t | | rea |
| Last | | | First | | Midd | le | Suffix | | | Unknown | | Not deplo | yed |
| Address | | | | | | | Stillix | | Race | Omerown | 100 | Deployed: | front |
| | | | | | | | | | | | ☐ 101 I | Deployed: | side |
| Street | - | | | Cit | v | | State | Postal Code | | | ☐ 102 l | Deployed: | curtain |
| Injury Status | Se | eating Pos | ition | Ejection | Ejectio | n Path | Extrication | Restraint Systems | Helmet | Used | | Deployed: | |
| T | | | | | | | | | | | | Not applic | able |
| Type of Medical | EMS | Notified | | | | Transporte | d To Medical Facilit | ty By | Eye Pro | otection | 999 | Jnknown | |
| Transportation | | | | | | | | | | | If 198 is ch | ecked, des | cribe below |
| | | M/DD/YYYY) Arrived | | Time (HH:MM AM/PM) | | | | | Trauma | Band # | 7 | | |
| | LIVIS / | Arrived | | | 1 | Medical Fa | cility Transported T | o | | | | | |
| | Data (M | | | _ | | | | | | | 1 | | |
| MOTOR VEHIC | | IM/DD/YYYY) | of the late | Time (HH:MM AM/PM) | | | | | | | | | |
| Name | | | Section Processing | | Mess | | | Date of Birth/Age | | Mala | PASSEN | | |
| | | | | | | | | Date of BirtinAge | _ | Female | Air Bag Check all th | | ea |
| ast | | | First | | Middle | 9 | Suffix | | _ | Unknown | | Not deploy | red |
| Address | | | | | | | Strink | | Race | OTIKITOWIT | 100 0 | Deployed: | front |
| | | | | | | | | | | | ☐ 101 E | Deployed: | side |
| Street | | | | City | , | | State | Postal Code | | | ☐ 102 E | eployed: | curtain |
| njury Status | Sea | ating Posi | tion | Ejection | Ejection | n Path | Extrication | Restraint Systems | Helmet | Used | | eployed: | |
| Turnet | | | | | | | | | | | ☐ 970 N | | able |
| Type of Medical | EMS | Notified | | | 1 | Transported | d To Medical Facility | у Ву | Eye Pro | tection | 999 U | Inknown | |
| ransportation | | | | | | | | | | | If 198 is che | ecked, des | cribe below |
| | | Arrived | | Time (HH:MM AM/PM) | | 4 | | | Trauma | Band # | | | |
| | LINIO / | anveu | | | . [| Medical Fac | ility Transported To | 0 | 1 | | | | |
| 2 | Data /A/A | M/DD/YYYY) | | T " " " | | | | | | | | | |
| 经证明的经济 | Sale TWI | | W. T. Sala | Time (HH:MM AM/PM) | | DAGGEN | | | | | | | |
| njury Status | | Ejection | Name of Street | Ejection Both | 1 | | GER CODES | | 以應用 | | | | |
| (K) Fatal injury | | 000 Not ejec | | Ejection Path 000 Not ejected | | | Systems Used | Vehicle Seating | Position | | | | |
| (A) Suspected seriou | s injury | 100 Ejected, | partially 1 | 100 Side door opening | | | sed - motor vehicle occupar er and lap belt used | Fron | 1 | 800 SI | eper section | of cab (tru | ıck) |
| (B) Suspected minor(C) Possible injury | injury | 101 Ejected, 970 Not appl | | 01 Side window | | 101 Shoulde | r belt only used | Row Left Middle | Right Ot | | ssenger sect | | |
| (O) No apparent injury | y | 999 Unknow | | 02 Windshield 03 Back window | | 102 Lap belt | only used It used - type unknown | 1 110 120 | 130 1 | | closed passe enclosed pas | | |
| Race | - | | 1 | 04 Back door/tailgate ope | ning | | straint system - forward fac | ing 2 210 220 | 230 2 | 804 Pa | ssenger/carg | o area, | ngo araa |
| 00 White/Caucasian | | Extrication | | 05 Roof opening (sun roof, convertible) | | 105 Child res | straint system - rear facing | 3 310 320 | 330 3 | | known if encl | osed | |
| 01 Black/African-Ame 02 Hispanic | rican | 000 Not extri | cated 1 | 06 Roof (convertible top u | (q) | 106 Booster 107 Child res | seat straint - type unknown | 4 410 420 | | 806 Ric | ding on motor | vehicle ex | kterior |
| 33 Asian/Pacific Islan | der | 100 Extricate | d 1 | 98 Other (e.g., back of pie | kup truck, | 198 Other | | 5 510 520 | 530 5 | 999 Un | known | | |
| 04 American Indian | | 999 Unknow | 1 9 | torn-off roof, car cut in 70 Not applicable | half) | 970 Not appl 999 Unknow | | Bus Seating Pos | ition (us | e if 801 is | selected) | | |
| 98 Other 99 Unknown | | | | 99 Unknown | | JUG GIRIOWI | " | | | Front | | | |
| ype of Medical | Trans | portation | Motorcy | cle Helmet Used | | Eye Prote | ection Used | Driver | | | | | |
| 00 Not transported | | | 000 No heli | met worn | | 000 No | | 1A 1B | 1C | | 1D | 1E | 1F |
| 00 EMS air 01 EMS ground | | | 100 DOT-c | ompliant motorcycle helm | et worn | 100 Yes | | 2A 2B | 2C | > | 2D | 2Ē | 2F |
| 2 Law enforcement | | | 102 Helmet | OT-compliant motorcycle t worn, unknown if DOT-c | nelmet wor | rn 999 Unknowr | 1 | 3A 3B | 3C | Aisle | 3D | 3E | 3F |
| 8 Other | -111 | | 999 Unknow | wn if helmet worn | pmunt | | | | : | | : | : | : |
| 9 Transported, but m 9 Unknown if transpo | | nknown | | | | | | ##4 ##5 | | - | | | - |
| | | | | | | | | ##A ##B | ##C | | ##D | ##E | ##F |
| | | | | | | | | | CF | RASH REPOR | T - PASSENC | ER INFOR | RMATION |

ARKANSAS MOTOR VEHICLE CRASH REPORT NARRATIVE Page Crash Report # 230322134

Page 12 of 13

V-1 WAS WESTBOUND ON BRUCE STREET. V-2 WAS SOUTHBOUND IN THE #2 LANE ON HARKRIDER. BOTH V-1 AND V-2 WERE APPROACHING THE INTERSECTION OF HARKRIDER AND BRUCE STREET, THAT'S WHEN V-2 ACTIVATED HIS EMERGENCY LIGHTS AND SIRENS, DUE TO A DISPATCHED CALL AS V-2 WAS ENTERING THE INTERSECTION, V-1 WAS ALSO ENTERING THE INTERSECTION, CAUSING THE FRONT OF V-1 TO COLLIDE WITH THE LEFT SIDE OF V-2 (P.O.I 1). THE IMPACT DEFLECTED V-2 IN A SOUTHWEST DIRECTION, CAUSING THE FRONT OF THE VEHICLE TO COLLIDE WITH A TRAFFIC LIGHT POLE (P.O.I 2). THE IMPACT WITH V-2 CAUSED V-1 TO ROATATE COUNTER CLOCKWISE AT THE INTIAL POINT OF IMPACT (P.O.I 1). V-1 CAME TO FINAL REST PARTIALLY IN THE SOUTHBOUND #2 LANE AND CENTER TURN LANE IN THE INTERSECTION, FACING SOUTHEAST. V-2 CAME TO FINAL REST AT POINT OF IMPACT 2 (P.O.I 2), FACING SOUTHWEST.

513239



Date: 3/9/2022 11:29 AM

Page 1 of 8

Estimate ID: EA-04969

Estimate Version: 0

Preliminary

Profile ID: * PRO AUTO

UNIT #1808

ECLIPSE APPRAISAL INC

Damage Assessed By: Curtis Russell

Supplements to Curtis Russsell (curtis@eclipseappraisal.com)

Type of Loss: Collision

Arrival Date: 3/ 9/2022 Accident Date: 3/ 5/2022

Drive Train: 3.6L Inj 6 Cyl 5A RWD License: 568VUY AR

(501) 977-4436

Vehicle Production Date: 2/8

Classification: Field

Condition Code: Good

Date of Loss: 3/ 5/2022 Contact Date: 3/9/2022 Deductible: 500.00

File Number: EA-04969 Claim Number: AAC-0039445

> Insured: FAULKNER CO. SHERIFF DEPT Owner: FAULKNER CO. SHERIFF DEPT Address: 801 LOCUST ST., CONWAY, AR 72032 Telephone: Work Phone: (501) 450-4914

> > Mitchell Service: 911667

Description: 2018 Dodge Charger Police

Body Style: 4D Sed

VIN: 2C3CDXAG3JH253319

Mileage: 89,369

OEM/ALT: A

Parts Profile: Little Rock

Color: WHITE

Parts Profile Version: 2

Options: PASSENGER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING POWER BRAKE, REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN

FM RADIO, ANTI-LOCK BRAKE SYS., TIRE INFLATION/PRESSURE MONITOR

| Line Item | Entry Number | Labor Type | Operation | Line Item Description | Part Type/ Part Number | Dollar Amount | Labor Units |
|--------------|-----------------|---------------|------------------------|-------------------------------------|---------------------------|------------------|----------------|
| | | | | Front Bumper | | | |
| 1 | 100387 | BDY | OVERHAUL | Frt Bumper Cover Assy | | | 4.0 # |
| 2 | 102899 | BDY | REMOVE/REPLACE | Frt Bumper Cover | ** QRP Certified | 644.00 | INC # |
| 3 | | REF | REFINISH | Frt Bumper Cover | an continua | | C 2.7 # |
| 4 | 100935 | BDY | REMOVE/REPLACE | R Frt Bumper Bracket | ** QUAL REPL PART | 27.00 | INC # |
| 5 | 100936 | BDY | REMOVE/REPLACE | L Frt Bumper Bracket | ** QUAL REPL PART | 27.00 | |
| 6 | 100937 | BDY | REMOVE/REPLACE | R Frt Bumper Support Bracket | ** QUAL REPL PART | | INC # |
| 7 | | BDY | REMOVE/INSTALL | Frt Bumper Cover | GOAL REPL PART | 8.00 | INC # |
| 8 | 100938 | BDY | REMOVE/REPLACE | L Frt Bumper Support Bracket | ** QUAL REPL PART | 2.00 | INC # |
| 9 | 103658 | BDY | REMOVE/REPLACE | Frt Bumper License Plate Bracket | | 8.00 | INC # |
| 10 | 100939 | BDY | REMOVE/REPLACE | R Frt Otr Bumper Reinforcement | ** QUAL REPL PART | 45.00 | INC |
| 11 | 100940 | BDY | REMOVE/REPLACE | L Frt Otr Bumper Reinforcement | ** QUAL REPL PART | 27.00 | INC |
| 12 | 100931 | BDY | REMOVE/REPLACE | Frt Lwr Bumper Grille | ** QUAL REPL PART | 27.00 | INC |
| 13 | 100947 | BDY | REMOVE/REPLACE | | 68240583AB | 83.65 | INC # |
| 14 | 100948 | BDY | REMOVE/REPLACE | R Frt Bumper Fog Lamp Opening Cover | ** QUAL REPL PART | 39.00 | INC # |
| 15 | 100945 | BDY | REMOVE/REPLACE | L Frt Bumper Fog Lamp Opening Cover | ** QUAL REPL PART | 39.00 | INC # |
| 16 | 100946 | BDY | REMOVE/REPLACE | Frt Bumper Energy Absorber | ** QRP Certified | 85.00 | INC # |
| 17 | 100010 | | NEWOVE/REPLACE | Frt Bumper Reinforcement Bar (UHSS) | Qual Recycled Part | 150.00 * | 1.0 #r |
| | | | | Line Markup %25.00 | | 37.50 | |
| 18 | 101091 | BDY | DEMOVE/DEDI 405 | Grille | | | |
| 10 | 101091 | 501 | REMOVE/REPLACE | Grille | ** QRP Certified | 318.00 | INC # |
| EST | IMATE RE | CALL NU | MBER: 03/09/2022 10:47 | 7:16 EA-04969 | | | |

Mitchell Data Version: OEM: FEB_22_V

Alternate Parts: 03/09/2022 11:02:05

Software Version:

7.1.242

Copyright (C) 1994 - 2022 Mitchell International All Rights Reserved

Page 2 of 8

Date: 3/9/2022 11:29 AM Estimate ID: EA-04969

Estimate Version: 0

Preliminary
Profile ID: * PRO AUTO

| | | | | Front Lamps | Profile ID: | PRO AUTO | | |
|----|--------|-----|----------------|---|--|---|-------|-----|
| 19 | 103553 | | REMOVE/REPLACE | R Frt Combination Lamp Assembly | 68541680AA | 747.00 | INC | C# |
| 20 | | BDY | CHECK/ADJUST | Headlamps | | | 0. | |
| 21 | 103566 | | REMOVE/REPLACE | L Frt Combination Lamp Assembly | 68541681AA | 947.00 | | C # |
| 22 | 100718 | | REMOVE/REPLACE | R Front Side Marker Lamp Assembly | ** QUAL REPL PART | 35.00 | | C # |
| 23 | 100719 | BDY | REMOVE/REPLACE | L Front Side Marker Lamp Assembly _ Hood | ** QUAL REPL PART | 35.00 | | C # |
| 24 | 100559 | BDY | REMOVE/REPLACE | Hood Panel (Alum) | Qual Recycled Part | 685.00 | * 16 | 6 r |
| 25 | | REF | REFINISH | Hood Outside | addi Hooyolea i art | 003.00 | C 2.8 | |
| 26 | | REF | REFINISH | Add For Hood Underside | | | C 1.4 | |
| 27 | | | | Line Markup %25.00 | | 171.25 | 0 1 | • |
| 28 | 100592 | BDY | REMOVE/REPLACE | Hood Latch | 55113787AB | 89.00 | INC | . # |
| 29 | 100577 | | REMOVE/REPLACE | Hood Striker | 4589689AA | 28.00 | INC | |
| 30 | 100579 | BDY | REMOVE/REPLACE | Hood Release Cable | 1PS72DX9AC | 99.35 | | 3 # |
| | | | | Cooling | | *************************************** | 0.0 | |
| 31 | 100472 | BDY | REMOVE/REPLACE | Cooling Radiator | ** QUAL REPL PART | 225.99 | INC | : # |
| 32 | | BDY | REMOVE/INSTALL | Air Cleaner Assy | | | 0.5 | |
| 33 | | BDY | REMOVE/REPLACE | Vacuum-Fill & Bleed Cooling System | | | 0.6 | |
| 34 | 100473 | BDY | REMOVE/REPLACE | R Upr Cooling Insulator | 4596474AD | 24.45 | 0.0 | |
| 35 | 100474 | BDY | REMOVE/REPLACE | L Upr Cooling Insulator | 4596474AD | 24.45 | | |
| 36 | 100479 | BDY | REMOVE/REPLACE | Upr Cooling Radiator Seal | ** QUAL REPL PART | 64.00 | | |
| 37 | 100480 | BDY | REMOVE/REPLACE | R Cooling Radiator Seal | ** QUAL REPL PART | 45.00 | | |
| 38 | 100481 | BDY | REMOVE/REPLACE | L Cooling Radiator Seal | ** QUAL REPL PART | 45.00 | | |
| 39 | 102110 | BDY | REMOVE/REPLACE | R Cooling Air Deflector Seal | " QUAL REPL PART | 21.00 | | |
| 40 | 102111 | BDY | REMOVE/REPLACE | L Cooling Air Deflector Seal | ** QUAL REPL PART | 21.00 | | |
| 41 | 100482 | BDY | REMOVE/REPLACE | Lwr Cooling Radiator Seal | ** QUAL REPL PART | 64.00 | | |
| 42 | 100483 | BDY | REMOVE/REPLACE | Lwr Cooling Seal | 5112199AB | 40.10 | | |
| 43 | 100484 | BDY | REMOVE/REPLACE | Cooling Fan Module | ** QUAL REPL PART | 205.07 | INC | # |
| 44 | 100488 | BDY | REMOVE/REPLACE | Cooling Fluid Reservoir | ** QUAL REPL PART | 75.00 | 0.5 | |
| | | | | A/C /Heater/Ventilation | | | 0.5 | |
| 45 | 101057 | MCH | REMOVE/REPLACE | A/C Condenser/Trans Cooler -M | ** QUAL REPL PART | 244.90 | 1.3 | # |
| 46 | | MCH | REMOVE/REPLACE | Evacuate & Recharge A/C -M | | 211.50 | 1.4 | |
| | | | | _Front Fender | | | 1.7 | |
| 47 | 101042 | BDY | REMOVE/REPLACE | R Fender Panel | Qual Recycled Part | 200.00 | * 0.9 | #r |
| 48 | | REF | REFINISH | R Fender Outside | | | C 1.6 | 11 |
| 49 | | REF | REFINISH | R Add To Edge Fender | | | C 0.5 | |
| 50 | | | | Line Markup %25.00 | | 50.00 | 0.5 | |
| 51 | 101043 | BDY | REMOVE/REPLACE | L Fender Panel | Qual Recycled Part | 210.00 | 0.9 | #= |
| 52 | | REF | REFINISH | L Fender Outside | and the system of the system o | | C 1.6 | #1 |
| 53 | | REF | REFINISH | L Add To Edge Fender | | | C 0.5 | |
| 54 | | | | Line Markup %25.00 | | 52.50 | 0.5 | |
| 55 | 103096 | BDY | REMOVE/REPLACE | R Fender Silencer | 68253191AB | 62.80 | | |
| 56 | 103097 | BDY | REMOVE/REPLACE | L Fender Silencer | 68253191AB | 62.80 | | |
| 57 | 101045 | BDY | REMOVE/REPLACE | L Fender Sound Absorber | 68043211AD | 12.30 | | |
| 58 | 102438 | BDY | REMOVE/REPLACE | R Fender Splash Shield | ** QUAL REPL PART | 105.00 | INC | |
| 59 | 102439 | BDY | REMOVE/REPLACE | L Fender Splash Shield | 68205937AG | 128.00 | INC | |
| | | | | Front Inner Structure | | 120.00 | | |
| 60 | 100524 | BDY | REMOVE/REPLACE | Frt Body Upper Crossmember | ** QUAL REPL PART | 271.00 | 2.0 | # |
| 61 | | MCH | REMOVE/REPLACE | Add To R&I/R&R Mechanical Components -M | | 271.00 | 0.5 | |
| 62 | | REF | REFINISH | Upr Rad Supt Crossmember | | | 1.5 | # |
| 63 | 100526 | BDY | REMOVE/REPLACE | Frt Body Lower Tie Bar | ** QUAL REPL PART | 246.00 | 0.5 | |
| 64 | | REF | REFINISH | Lower Tie Bar | | 240.00 | 1.0 | |
| 65 | 102255 | BDY | REMOVE/REPLACE | R Frt Body Duct | 68205062AF | 119.00 | 0.2 | |
| 66 | 100447 | BDY | REMOVE/REPLACE | Frt Body Closing Panel | ** QUAL REPL PART | 153.00 | INC | # |
| 67 | | REF | REFINISH | R Apron/Lower Side Rail Complete | | . 55.00 | 1.5 | ır |
| 68 | | REF | REFINISH | L Apron/Lower Side Rail Complete | | | 1.5 | |
| | 100540 | BDY | REMOVE/REPLACE | R Frt Body Front Apron Panel (Steel/HSS) | 68444164AD | 161.00 | 5.5 | |
| | 100541 | BDY | REMOVE/REPLACE | L Frt Body Front Apron Panel (Steel/HSS) | 68444165AD | 179.00 | 5.5 | |
| 71 | 100545 | BDY | REMOVE/REPLACE | R Inr Frt Body Apron Reinf (HSS) -S | 68043926AD | 290.00 | INC | # |
| | 200 | | | | | 250.00 | INC | # |

ESTIMATE RECALL NUMBER: 03/09/2022 10:47:16 EA-04969

Mitchell Data Version: OEM: FEB_22_V

Alternate Parts: 03/09/2022 11:02:05

Software Version:

7.1.242

Copyright (C) 1994 - 2022 Mitchell International All Rights Reserved

Date: 3/ 9/2022 11:29 AM Estimate ID: EA-04969

Page 3 of 8

Estimate Version: 0

Preliminary

| | | | | | Profile ID: * | PRO AUTO |
|-----|--------|------------|----------------|-------------------------------------|---------------------------|-----------------|
| 72 | 100546 | BDY | REMOVE/REPLACE | L Inr Frt Body Apron Reinf (HSS) -S | 68043927AD | 316.00 INC # |
| 73 | 100543 | BDY | REMOVE/REPLACE | R Otr Frt Body Apron Reinf (HSS) -S | 68037592AA | 316.00 4.5 # |
| 74 | 100544 | BDY | REMOVE/REPLACE | L Otr Frt Body Apron Reinf (HSS) -S | 68037593AA | 316.00 4.5 # |
| 75 | 100547 | BDY | REMOVE/REPLACE | R Frt Body Side Rail Assy (HSS) -S | 68504488AA | 755.00 13.5 # |
| 76 | 100548 | BDY | REMOVE/REPLACE | L Frt Body Side Rail Assy (HSS) -S | 68504489AA | 303.00 13.5 # |
| 77 | 103215 | BDY | REMOVE/REPLACE | R Frt Body Bumper Reinforcement -S | ** QUAL REPL PART | 58.00 1.0 |
| 78 | 103216 | BDY | REMOVE/REPLACE | L Frt Body Bumper Reinforcement -S | ** QUAL REPL PART | 58.00 1.0 |
| 79 | 103805 | BDY | REMOVE/REPLACE | R Frt Body Support Bracket | 68249076AA | 8.80 |
| 80 | 103806 | BDY | REMOVE/REPLACE | L Frt Body Support Bracket | 68249077AA | 8.80 |
| 81 | 100553 | BDY | REMOVE/REPLACE | R Frt Body Rail Reinf (HSS) -S | 68230360AC | 275.00 INC |
| 82 | 100554 | BDY | REMOVE/REPLACE | L Frt Body Rail Reinf (HSS) -S | 68230361AC | 285.00 INC |
| 83 | 100555 | BDY | REMOVE/REPLACE | R Frt Body Extension (HSS) | 68250516AA | 43.65 |
| 84 | 100556 | BDY | REMOVE/REPLACE | L Frt Body Extension (HSS) | 68250517AA | 41.90 |
| 85 | 102257 | MCH | REMOVE/REPLACE | Sub-Frame -M | Qual Recycled Part | 400.00 * 6.0 #r |
| 86 | | | | Line Markup %25.00 | | 100.00 |
| | | | | Air Bag System | | |
| 87 | 102587 | MCH | REMOVE/REPLACE | Air Bag Module-Driver Front -M | 1ZZ44DX9AH | 1,035.00 INC |
| 88 | 102962 | MCH | REMOVE/REPLACE | Air Bag Clockspring -M | 6NE94DX9AC | 413.00 1.1 |
| 89 | 102261 | MCH | REMOVE/REPLACE | Air Bag Module-Passenger Front -M | 68282914AD | 631.00 INC # |
| 90 | | MCH | REMOVE/INSTALL | Instrument Panel Assy -M | | INC |
| 91 | 100052 | MCH | REMOVE/REPLACE | Air Bag Driver Knee Module -M | 5057792AH | 334.00 0.7 |
| 92 | 100397 | MCH | REMOVE/REPLACE | R Frt Air Bag Impact Sensor -M | 56054085AA | 193.00 INC # |
| 93 | 100398 | MCH | REMOVE/REPLACE | L Frt Air Bag Impact Sensor -M | 56054085AA | 193.00 INC # |
| 94 | 100408 | MCH | REMOVE/REPLACE | L Air Bag Side Curtain Module -M | 68222743AG | 290.00 INC # |
| 95 | | BDY | REMOVE/INSTALL | Roof Headliner | | INC # |
| | | | | Wheel | | |
| 96 | 100021 | BDY | REMOVE/REPLACE | Wheel 2@93.00 | Qual Recycled Part | 186.00 0.6 r |
| 97 | | | | Line Markup %25.00 | | 46.50 |
| 98 | 100065 | BDY | REMOVE/REPLACE | Wheel Cover 2@103.00 | ZY74ZDJAC | 206.00 |
| | | | | Front Suspension | | |
| 99 | 102064 | MCH | OVERHAUL | Frt Susp Components Both Sides -M | | 11.4 |
| 100 | | | | DOES NOT INCLUDE ALIGNMENT | | |
| 101 | 102388 | MCH | REMOVE/REPLACE | R Frt Susp Steering Knuckle -M | Qual Recycled Part | 300.00 * INC #r |
| 102 | | | | Line Markup %25.00 | | 75.00 |
| 103 | 102389 | MCH | REMOVE/REPLACE | L Frt Susp Steering Knuckle -M | Qual Recycled Part | 300.00 * INC #r |
| 104 | | | | Line Markup %25.00 | | 75.00 |
| 105 | 100261 | MCH | REMOVE/REPLACE | R Upr Frt Susp Control Arm Assy -M | 68487350AA | 265.00 INC # |
| 106 | 100262 | MCH | REMOVE/REPLACE | L Upr Frt Susp Control Arm Assy -M | 68487351AA | 211.00 INC # |
| 107 | 100271 | MCH | REMOVE/REPLACE | R Lwr Frt Susp Control Arm Assy -M | 5168389AB | 214.00 INC # |
| 108 | 100272 | MCH | REMOVE/REPLACE | L Lwr Frt Susp Control Arm Assy -M | 5168389AB | 214.00 INC # |
| 109 | 100275 | MCH | REMOVE/REPLACE | R Frt Susp Strut Arm -M | ORDER FROM DEALER | 181.00 INC # |
| 110 | 100276 | MCH | REMOVE/REPLACE | L Frt Susp Strut Arm -M | ORDER FROM DEALER | 181.00 INC # |
| 111 | 100239 | MCH | REMOVE/REPLACE | R Frt Susp Strut -M | ORDER FROM DEALER | 134.00 INC # |
| 112 | 100240 | MCH | REMOVE/REPLACE | L Frt Susp Strut -M | ORDER FROM DEALER | 134.00 INC # |
| 113 | 100278 | MCH | REMOVE/REPLACE | Frt Susp Stabilizer Bar -M | Qual Recycled Part | 82.00 * INC #r |
| 114 | | | | Line Markup %25.00 | | 20.50 |
| 115 | 100287 | MCH | REMOVE/REPLACE | R Frt Susp Stabilizer Bar Link -M | 4895482AC | 60.50 INC # |
| 116 | 100288 | MCH | REMOVE/REPLACE | L Frt Susp Stabilizer Bar Link -M | 4895483AC | 60.75 INC # |
| | | | | Front Steering Linkage/Gear | | |
| 117 | 101140 | MCH | REMOVE/REPLACE | Steering Gear Assembly -M | Qual Recycled Part | 410.00 * 2.4 r |
| 118 | | | | Line Markup %25.00 | | 102.50 |
| 440 | 404040 | | | Windshield | | |
| 119 | 101240 | GLS | REMOVE/REPLACE | W/Shield Glass | DW02175GTY | 490.95 INC # |
| 120 | 101232 | BDY | REMOVE/REPLACE | L W/Shield Pillar Garnish | 5LN25DX9AF | 69.35 INC |
| 101 | 100007 | MOU | DEMOVE PER LOS | Instrument Panel | | |
| 121 | 102627 | MCH | REMOVE/REPLACE | Inst Panel -M | ORDER FROM DEALER | 1,380.00 7.5 |
| 122 | 101204 | BOY | DEMOVE/DEDLAGE | Rocker/Pillars/Floor | | |
| 123 | 101304 | BDY REF | REMOVE/REPLACE | L Door Opening Panel | 68265441 A F | 745.00 19.2 # |
| 123 | | HEP | REFINISH | L Door Opening Panel Complete | | C 3.8 |
| | | | | | | |

Alternate Parts: 03/09/2022 11:02:05 Copyright (C) 1994 - 2022 Mitchell International

All Rights Reserved

ESTIMATE RECALL NUMBER: 03/09/2022 10:47:16 EA-04969

7.1.242

Mitchell Data Version: OEM: FEB_22_V

Software Version:

Date: 3/9/2022 11:29 AM

Estimate ID: EA-04969

Estimate Version: 0

Preliminary

Profile ID: * PRO AUTO

| | | | | | | Profile ID: P | RO AUTO | | | |
|---|-----|--------|-----|-------------------|---|--------------------|----------|---|-----|-----|
| | 124 | | MCH | REMOVE/REPLACE | L Add To R&I/R&R Side Curtain Air Bags-M | | | | 0.8 | 3 # |
| | 125 | | MCH | REMOVE/REPLACE | L Ctr Add To R&I/R&R Side Air Bag Sensor | | | | 0.3 | 3 # |
| | 126 | | MCH | REMOVE/REPLACE | L Rear Add To R&I/R&R Side Air Bag Senso | | | | 0.3 | 3 # |
| | 127 | 101391 | BDY | REMOVE/REPLACE | R Rocker Moulding | 1LP86TZZAG | 354.00 |) | INC | |
| | 128 | | REF | REFINISH | R Rocker Moulding | | | C | 1.0 |) |
| | 129 | 101392 | BDY | REMOVE/REPLACE | L Rocker Moulding | 1LP87TZZAG | 415.00 | | INC | |
| | 130 | | REF | REFINISH | L Rocker Moulding | | | С | 1.0 |) |
| | 131 | 101398 | BDY | REMOVE/REPLACE | L Ctr Pillar Trim Panel | 1KL29DX9AI | 209.00 | | INC | |
| | | | | | Seat Belts | | | | | |
| | 132 | 101405 | BDY | REMOVE/REPLACE | R Frt Seat Belt | ORDER FROM DEALER | 295.00 | | 1.2 | # |
| | 133 | 101406 | BDY | REMOVE/REPLACE | L Frt Seat Belt | ORDER FROM DEALER | 288.00 | | 0.4 | |
| | 134 | 101475 | BDY | REMOVE/REPLACE | R Frt Seat Belt Adjuster | 68080745AD | 50.55 | | | |
| | 135 | 101476 | BDY | REMOVE/REPLACE | L Frt Seat Belt Adjuster | 68080745AD | 50.55 | | | |
| | 136 | 102875 | BDY | REMOVE/REPLACE | R Frt Seat Belt Buckle | ORDER FROM DEALER | 209.00 | | 0.2 | # |
| | 137 | | BDY | REMOVE/INSTALL | R Seat Assy | | | | 0.4 | |
| | 138 | 102876 | BDY | REMOVE/REPLACE | L Frt Seat Belt Buckle | ORDER FROM DEALER | 196.00 | | 0.2 | |
| | 139 | | BDY | REMOVE/INSTALL | L Seat Assy | | 100.00 | | 0.4 | |
| | | | | | Front Door | | | | 0.4 | |
| | 140 | 101425 | BDY | REMOVE/REPLACE | L Frt Door Shell (Steel/HSS) | 68268055AC | 905.00 | | 5.0 | # |
| | 141 | | REF | REFINISH | L Frt Door Outside | 0020000000 | 303.00 | | 1.9 | # |
| | 142 | | REF | REFINISH | L Frt Add For Jambs & Interior | | | | 1.0 | |
| | | | | | Rear Door | | | • | 1.0 | |
| | 143 | 100731 | BDY | REMOVE/REPLACE | L Rear Door Shell (Steel/HSS) | Qual Recycled Part | 500.00 | * | 5.0 | #= |
| | 144 | | REF | REFINISH | L Rear Add For Jambs & Interior | dual necycled Part | 300.00 | | 1.0 | #1 |
| | 145 | | REF | REFINISH | L Rear Door Outside | | | | 1.8 | |
| | 146 | | | | Line Markup %25.00 | | 125.00 | • | 1,0 | |
| | | | | | Roof | | 125,00 | | | |
| | 147 | 101694 | BDY | REPAIR | Roof Panel | Existing | | | 8.0 | |
| | 148 | | REF | REFINISH | Roof Panel Outside | Existing | | _ | 2.5 | |
| | 149 | 101698 | BDY | REMOVE/INSTALL | Roof Antenna | | | C | | |
| | 150 | 102695 | BDY | REMOVE/REPLACE | Roof Headliner | ORDER FROM DEALER | 1 015 00 | | 0.4 | |
| | 151 | | GLS | REMOVE/INSTALL | Windshield | ORDER FROM DEALER | 1,045.00 | | 4.4 | |
| | | | | TEMO VENITO I ALL | Quarter Panel | | | | INC | # |
| | 152 | 100792 | BDY | REMOVE/REPLACE | L Rear Quarter Pillar Trim Panel | 00000 5004 054 50 | | | | |
| | | 100702 | | TEMOVE/TEPEACE | | ORDER FROM DEALER | 97.65 | | 0.2 | |
| - | 153 | 103148 | BDY | REMOVE/REPLACE | <u>Luggage Lid</u> Luggage Lid Panel | 0 15 15 | | | | |
| | 154 | 100140 | REF | REFINISH | | Qual Recycled Part | 400.00 | | 1.8 | r |
| | 155 | | BDY | REMOVE/REPLACE | Luggage Lid Outside Add w/Rear View Camera | | | С | 2.2 | |
| | 156 | | REF | REFINISH | | | | | 0.4 | |
| | 157 | | NEF | RELINION | Luggage Lid Underside | | | С | 1.0 | |
| | 137 | | | | Line Markup %25.00 | | 100.00 | | | |
| 4 | 158 | 936012 | | ADDU COCT | Additional Costs & Materials | | | | | |
| | 159 | | | ADD'L COST | Hazardous Waste Disposal | | 5.00 | | | |
| | 139 | 936014 | | ADD'L COST | Flex Additive | | 8.00 | * | | |
| | 160 | | DEE | ADDII ODE | Additional Operations | | | | | |
| | 160 | 022040 | REF | ADD'L OPR | Clear Coat | | | | 5.8 | |
| 1 | 161 | 933018 | REF | ADD'L OPR | Mask For Overspray | | 10.00 | * | | |
| | 162 | | | ADDII COCT | Additional Costs & Materials | | | | | |
| 1 | 102 | | | ADD'L COST | Paint/Materials | | 1,504.80 | * | | |
| | | | | | | | | | | |

^{* -} Judgment Item

ESTIMATE RECALL NUMBER: 03/09/2022 10:47:16 EA-04969

Mitchell Data Version: OEM: FEB_22_V

Alternate Parts: 03/09/2022 11:02:05

Software Version:

7.1.242

Copyright (C) 1994 - 2022 Mitchell International All Rights Reserved

^{# -} Labor Note Applies

^{**} QRP Certified - Quality Replacement Parts - Certified

^{**} QUAL REPL PART - Quality Replacement Parts

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

Date: 3/9/2022 11:29 AM

Estimate ID: EA-04969

Estimate Version: 0

45.00

45.00

Preliminary

Profile ID: * PRO AUTO

KEYSTONE KEYSIQ **25631 INTERSTATE 30** BRYANT AR 72022 (501) 847-7730 (877) 847-1200

KEYSTONE-INS QUALITY PRT 25631 INTERSTATE 30 BRYANT AR 72022

(501) 847-7730 (877) 847-1200 ** CH1218121

** CH1218121

37

38

| 2 | ** CH1000A24C | 644.00 |
|----|---------------|--------|
| 4 | ** CH1043111 | 27.00 |
| 5 | ** CH1042111 | 27.00 |
| 6 | ** CH1043118 | 8.00 |
| 8 | ** CH1042118 | 8.00 |
| 9 | ** CH1068145 | 45.00 |
| 10 | ** CH1043112 | 27.00 |
| 11 | ** CH1042112 | 27.00 |
| 13 | ** CH1039169 | 39.00 |
| 14 | ** CH1038169 | 39.00 |
| 15 | ** CH1070836C | 85.00 |
| 18 | ** CH1200388C | 318.00 |
| 22 | ** CH2551133C | 35.00 |
| 23 | ** CH2550133C | 35.00 |
| 31 | ** RAD13157 | 225.99 |
| 36 | ** CH1218120 | 64.00 |
| 39 | ** CH1218107 | 21.00 |
| 40 | ** CH1218106 | 21.00 |
| 41 | ** CH1218120 | 64.00 |
| 43 | ** CH3115169 | 205.07 |
| 44 | ** CH3014152 | 75.00 |
| 45 | ** CND3948 | 244.90 |
| 58 | ** CH1249171 | 105.00 |
| 60 | ** CH1225280C | 271.00 |
| 63 | ** CH1225198C | 246.00 |
| 66 | ** CH1224101C | 153.00 |
| 77 | ** CH1063109 | 58.00 |
| 78 | ** CH1062109 | 58.00 |
| | | |

ESTIMATE RECALL NUMBER: 03/09/2022 10:47:16 EA-04969

Mitchell Data Version: OEM: FEB_22_V

Alternate Parts: 03/09/2022 11:02:05

Software Version:

7.1.242

Copyright (C) 1994 - 2022 Mitchell International All Rights Reserved

Date: 3/ 9/2022 11:29 AM Estimate ID: EA-04969

Estimate Version: 0

Preliminary

Profile ID: * PRO AUTO

Recycler Information Section:

Pratt's Auto Salvage and Sales 170 Industrial Drive PO Box 9 Hoxie AR 72433 800-348-6680;870-886-1510

| 85 2017 Dodge Part Number: H00290 | CHARGER | POLICE PACKAGE | VA | 400.00 |
|--|----------------------------------|---------------------------|---|--------|
| Description:5.7L,AOD, SUSP CROSSM | EMBED/SUBEDAME | | | |
| 101 2013 Dodge | | _ | | |
| Part Number: I90331 | CHARGER | R. | VA | 300.00 |
| Description PH 11 10 COL ADO DIOLE | - KAN 101/1 = 100 | | | |
| Description:RH,11-12,COL,ABS, RIGHT | | | | |
| 103 2013 Dodge | CHARGER | L. | VA | 300.00 |
| Part Number: I90331 | | | | |
| Description:LH,11-12,COL,ABS, LEFT | KNUCKLE/SPINDLE FRONT | | | |
| 143 2011 Dodge | CHARGER | L. | VA | 500.00 |
| Part Number: L60383 | | | • | 300.00 |
| Description:LH,WHT,4DR,PW,PL,DING | LEFT REAR SIDE DOOR | | | |
| 153 2015 Dodge | CHARGER | CAMERA | VA | 400.00 |
| Part Number: B80036 | | CAMETA | VA | 400.00 |
| Description: WHT, LOOK AT DINGS, LID | & GATE | | | |
| , | u drift | | | |
| J.B.'s Auto Salvage, Inc | | | | |
| 7018 Peters Rd. | | | | |
| Jacksonville AR 72076 | | | | |
| | | | | |
| 800-325-4442;501-985-1680 | | | | |
| 16 0000 Pada | | | | |
| 16 2008 Dodge | CHARGER | | VA | 150.00 |
| Part Number: 013612 | | | | |
| Description:06-18, FRONT BUMPER RE | INFORCEMENT | | | |
| | | | | |
| LKQ-Keystone- Preferred | | | | |
| 650 Simon Road | | | | |
| Conway AR 72032 | | | | |
| 800-233-3513;501-336-8654 | | | | |
| | | | | |
| 24 2015 Dodge | CHARGER | W/O HOOD SCOOP | *** | |
| Part Number: \$PT110 | o | W/O HOOD SCOOP | VA | 685.00 |
| Description:W/O HOOD SCOOP, HOOD | | | | |
| 47 2016 Dodge | CHARGER | _ | | |
| Part Number: \$PW288 | CHARGER | R. | VA | 200.00 |
| Description:RH,R., RIGHT FENDER | | | | |
| | | | | |
| 51 2016 Dodge | CHARGER | L, | VA | 210.00 |
| Part Number: \$PW288 | | | | |
| Description:LH,SXT,4DR L, L., LEFT FEN | IDER | | | |
| 96 2019 Dodge | CHARGER | 5 SPOKE | VA | 93.00 |
| Part Number: \$PT806 | | | *** | 33.00 |
| Description:POLICE,4DR 18X7-1/2, STEE | L, 5 SPOKE, WHEEL | | | |
| 113 2018 Dodge | CHARGER | PERFORMANCE SUSPENSION (O | VA | 00.00 |
| Part Number: \$PW795 | * | | VA | 82.00 |
| Description:POLICE, 5.7, RWD REAR, RW | D. HEAVY DUTY SUS. STARII IZED B | AB | | |
| 117 2018 Dodge | CHARGER | | | |
| Part Number: \$PW795 | V. ITALEIT | SPORT SUSPENSION (OPT SDE | VA | 410.00 |
| Description:(POWER RACK AND PINION |) ELECTRIC DWD STEERING OF A | 4004 | | |
| | ,, LLLOTAIC, KWD,, STEEKING GEAR | ASSY | | |
| | | | | |

Disclaimer: Recycled part pricing may represent either actual pricing (the price at which the recycler is willing to sell the part for in its existing condition) or undamaged pricing (the price at which the recycler would sell the part if it was in undamaged condition). If you are unsure, please contact the automotive recycler.

ESTIMATE RECALL NUMBER: 03/09/2022 10:47:16 EA-04969

Mitchell Data Version: OEM: FEB_22_V

Alternate Parts: 03/09/2022 11:02:05 Copyright (C) 1994 - 2022 Mitchell International

Software Version:

7.1.242

All Rights Reserved

Date: 3/9/2022 11:29 AM

Estimate ID: EA-04969 Estimate Version: 0

Preliminary

Profile ID: * PRO AUTO

Estimate Totals

| I. | Labor Subtotals Body Refinish Mechanical | Units 110.7 39.6 33.7 Taxable L Labor | Add'l Labor Amount 0.00 10.00 0.00 | Sublet Amount 0.00 0.00 0.00 0.00 | 2,306.80 | _ II. T T T | Taxable Parts Parts Adjustments | @ 7.500% t | Amount 24,606.31 955.75 1,917.15 27,479.21 |
|------|---|--|---|--|--|----------------------|---|---------------|---|
| III. | Total Additiona | Sales Tax | @ 7.5 | 00% | Amount 1,517.80 113.84 1,631.64 | IV. | Adjustments Insurance Deductible Customer Responsibility | | Amount 500.00- 500.00- |
| | Paint Material I Init Rate = 38.0 | | 9.9, Addi Rate | = 0.00 | | I. II. III. | Total Labor: Total Replacement Parts: Total Additional Costs: Gross Total: Total Adjustments: Net Total: | | 12,859.80 27,479.21 1,631.64 41,970.65 500.00- 41,470.65 |

This is a preliminary estimate. Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

12 Front Center (P), 1 Right Front Corner (S), 2 Right Front Side (S), 9 Left Side (S), 10 Left Front Side (S) 11 Left Front Corner (S)

Insurance Co: ARKANSAS ASSOCIATION OF COUNTIES

Address: 1415 WEST 3RD STREET

LITTLE ROCK, AR 72201

Telephone: (501) 375-8805

Inspection Site: PRO AUTO COLLISION

Inspection Date: 3/9/2022

ESTIMATE RECALL NUMBER: 03/09/2022 10:47:16 EA-04969

Mitchell Data Version: OEM: FEB_22_V

Alternate Parts: 03/09/2022 11:02:05

Software Version:

7.1.242

Copyright (C) 1994 - 2022 Mitchell International All Rights Reserved

Date: 3/9/2022 11:29 AM

Estimate ID: EA-04969

Estimate Version: 0 Preliminary

Profile ID: * PRO AUTO

Body Shop: PRO AUTO COLLISION REPAIR CENTER

Address: 6 RANCHETTE RD

CONWAY, AR 72032

Telephone: (501) 513-9200

Fax Phone: (501) 513-9810 Federal Tax ID 71-0858694

Email: scott@proautoconway.com

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. THE AFTERMARKET CRASH PARTS USED IN THE PREPARATION OF THIS ESTIMATE ARE WARRANTED BY THE MANUFACTURER OR DISTRIBUTOR OF SUCH PARTS INSTEAD OF THE MANUFACTURER OF YOUR VEHICLE.

DISCLAIMER: This estimate has been prepared by an independent appraisal service. Receipt of this estimate copy from the appraisal service is not an authorization for repairs or a guarantee of payment.

ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL BEFORE REPAIRS BEGIN OR PARTS ARE ORDERED All supplements will require all parts invoices for the entire repair. Failure to obtain approval may result in the denial of the payment for any and all supplemental repairs. -Please present this estimate to the shop of your choice -Only you can authorize repairs to your vehicle -If the shop has any questions about the estimate or if the shop encounters any supplemental damage, they should contact the appraiser's name listed on this estimate

LD. POWER Used Cars/Trucks

Eclipse Appraisal Inc.

PO BOX 84 Solgohachia, AR 72156 5019774436 curtis@eclipseappraisal.com

Vehicle Information

Vehicle:

2018 Dodge Charger Sedan 4D Police 3.6L V6

Reference #:

AAC-0039445

Region:

Central

Period:

March 5, 2022

VIN:

2C3CDXAG3JH253319

Mileage:

89,369

J.D. POWER Used Cars/Trucks Values

| | Base | Mileage Adj. | Option Adj. | Adjusted Value | |
|---|---------------|--------------|----------------|----------------|--|
| Clean Retail | \$24,425 | -\$1,975 | \$300 | \$22,750 | |
| Selected Options | | т., | ada lu /l a au | Retail | |
| Blind Spot Monitor [VIN Pre | ecision+1 | In | Trade-In/Loan | | |
| _ | • | | \$100 | \$125 | |
| Rear Parking Sensors [VIN Precision+] \$100 | | \$100 | \$125 | | |
| Heated Exterior Mirrors [VIII | N Precision+] | | \$50 | \$50 | |

Eclipse Appraisal Inc. Total Loss Evaluation

| Claim Rep Name/ID Number: Riley Gro | CI | Claim Number: AAC-0039445 | | | | | | | | |
|--|---|---------------------------|--|----------|---|--------------|------------------|--|--|--|
| Insured's Name: Faulkner Co. Sheriff's Dept. | | | Owner's Name: Same | | | | | | | |
| | ip Code: <u>7203</u> | | | of Los | s: $\Box T(T)$ | neft) D | C(Other) | | | |
| Vehicle ID Number: 2C3CDXAG3 | | | 71- | | _ , , , , | , | 30(0101) | | | |
| State: AR Loss Date: 3/5/22 Year: 2018 Make: Dodge Model: Charger | | | | | | | | | | |
| Body Syle: ☐ 2DR ☐ 4DR ☐ Lift/Hatchback ☐ Convertible ☐ Wagon ☐ Pickup ☐ Van ☐ Utility ☐ Motorcycle | | | | | | | | | | |
| ☐ ½ Ton ☐ ¾ Ton ☐ 1 Ton ☐ Shortbed ☐ Longbed ☐ Cab & Chassis ☐ Fleetside ☐ Fenderside | | | | | | | | | | |
| Engine Detail: Size: 5.7 Cylinde | rs: 🔲 3 | □ 4 □ | | | | | Diesel | | | |
| Transmission: AT S6 S5 | □ S4 □ S3 | | 4W Mileage:89.3 | | _ | | | | | |
| POWER OPTIONS DÉCOR/CONVENIENCE PS Pwr Steering AC Air Conditioner | T 00 0: 0 | TRUCKS/VANS/ | | | Guide Boo | k NAD | ۸ | | | |
| ☑ PB Pwr Brakes ☑ RD Rear Defogger | ☐ SB Step Bumper☐ SW Sliding Rear Window | | ☐ FL Fog Lights ☐ BD Running Boards | | | | | | | |
| ☑ PG Pwr Windows ☑ TW Tilt Wheel ☑ PL Pwr Locks ☑ CC Cruise Control | ☐ XT Auxiliary | Fuel Tank | ☐ BL Bed Liners | | Month MARCH | | | | | |
| ☐ PC Pwr Pass Seat ☐ CS Cloth Seats | An Chrome Bed Halls | | | | | | | | | |
| □ LS Leather Seats RADIO □ DB 4 WhI Disc Brakes | ☐ MP Metallic☑ TG Tinted G | Paint | ☐ RB Roll Bar ☐ TB Tool Box (Permanent) ☐ GG Grill Guards ☐ PO P | | Base Book | (| 24,425 | | | |
| ☒ AM AM ☐ TL Telescopic Wheel ☒ FM FM ☐ AL Auto Load Level ☒ ST Stereo ☐ 3S 3 rd Seat (Wagons Only) | ☐ CI Soft Top ☐ HT Hard Top | | | | Miles + - | | -1,975 | | | |
| ☑ ST Stereo ☐ 3S 3 rd Seat (Wagons Only) ☐ CA Cassette ☐ 8P 8 Passenger ☑ SE Srch/Scan ☐ DA Dual Air Conditioning | OTHER OPTIONS | | DW Dual Rear Wheels | | Blind Spot Mon +\$12 | | +\$125 | | | |
| ☐ CD Single Disc ☐ CD Changer ROOF OPTIONS | ☐ WG Woodgra ☐ BN Body Sida ☑ BS Bucket Se | e Moldings | ☑ PM Power Mirrors ☑ PT Power Trunk | | Rear Park Sensor +\$125 | | | | | |
| ☐ EQ Equalizer ☐ VR Vinyl Roof | | | WP Rear Window Wiper RL Reclining Seats | | Heated Mi | rrors | +\$50 | | | |
| ☐ RF Cabriolet Roof WHEEL OPTIONS ☐ ES Electric Steel | ☐ PA Power An | itenna | | | N. C. | | | | | |
| □ AW Aluminum □ EG Electric Glass | | | | | | | | | | |
| ☐ AY Alloy ☐ MS Manual Steel | ADDDAICE | R C. Russell | | | | | | | | |
| ☐ LC Locking Wire ☐ MG Manual Glass ☐ SA Spoked Aluminum ☐ FR Flip Roof | 1 | | | | | | | | | |
| SY Styled Steel | LOCATION | Conway | | | | | | | | |
| ☐ WW Wire ☐ GT Glass T-Tops | PHONE 50 | 1 077 4426 | | | Total Retai | | | | | |
| ☐ WC Wire Covers ☐ RR Roof Rack | FHONE 50 | 1-977-4436 | | | Book Value | , | 22,750 | | | |
| Re-Place Pair Old damage, mechanical repair, interior trim, refinishing, and any missing interior equipment (battery, radio, spare, etc.) | | | | | | | | | | |
| | | | | | | | | | | |
| O R \ | | | | | | + | | | | |
| d e | | | | | | + | | | | |
| i a o o | | | | | | + | | | | |
| n Tire Tread Depth LF RF | LR | RR | Spare | Tire | s Net Amount | + | | | | |
| 9 | | | Total | Recondit | ioning Amount | | | | | |
| | | | | | | | | | | |
| Dealership DE. | ALER QUOTES | Phone | Calana | 00 | STOCK | | 01 | | | |
| Elite Motors | 251-22 | 20-2267 | Salespers Internet | ψΠ | Yes No | - | Quote 20.995 | | | |
| 2. Velishek Auto | | 60-0426 | Internet | | | | 19,995 | | | |
| 3. Chicago Motors | 773-37 | 78-9892 | Internet | • | | | 21,795 | | | |
| | | | | Aver | age of Quotes | | 20,928 | | | |
| Company | GE BIDS | | | | ACV CALC | LII ATIO | NIC | | | |
| 1. Copart | Person Phone | | Bid | | ACV CALCULA 1 Book Value \$ | | | | | |
| 2. Pratt's Auto Salvage | Adam | 870-886-7145 | 199 2183 | | Value of Quotes | \$ \$ | 22,750 20,928 | | | |
| 3. Russell Towing | Donnie | 501-354-8726 | 500 | | ines 1 & 2 | \$ | 21,839 | | | |
| Salvage Location Pro Auto, Conway Charges day 45 Towing 4 Re | | | | | nditioning + - | \$ | | | | |
| Additional Comments Lasked the lady at COPART twice about the value of the PRO Quote. She said | | | | | ested ACV Tax | \$ \$ | 21,839 | | | |
| \$199 | Turis 7 uni | | S. S. S. O. O GRIC | o dales | 140 | Ψ | | | | |
| | | | | 7 Gran | d Total | \$ | | | | |

